

知 S5130S-HI系列交换机有线802.1X使用windows自带客户端认证异常经验案例

802.1X 葛松涛 2020-08-30 发表

组网及说明

不涉及

问题描述

现场使用S5130S-HI系列交换机，结合第三方RADIUS服务器，进行终端电脑的有线802.1X认证，电脑直连交换机进行认证，但是发现认证通过后电脑无法正常上网，电脑使用的是windows自带的客户端进行的认证

过程分析

首先我们查看设备侧802.1X相关配置，可以看到现场使用的是EAP中继方式，但是配置上没有什么明显问题，且交换机与RADIUS服务器互ping可以通信。因为现场处于开局状态，只使用一个口进行测试，于是让现场直接收集debugging dot1x all和debugging radius all的信息，查看一下debug信息，观察是否是服务器的问题导致认证失败。

#

dot1x

dot1x authentication-method eap

#

radius scheme sensetimeradius

primary authentication 10.151.1.248

primary accounting 10.151.1.248

key authentication cipher \$c\$3\$VIUaBXvVhtV5Nna57g9popb7m+8SQ4MhU4Kxp8hnsQ==

key accounting cipher \$c\$3\$DhTobwxPpFz1WP1ZPkMr5nrNt0XxWRUD64W0P+edAQ==

user-name-format without-domain

#

domain sensetimeradius

authentication lan-access radius-scheme sensetimeradius

authorization lan-access radius-scheme sensetimeradius

accounting lan-access radius-scheme sensetimeradius

#

interface GigabitEthernet1/0/6

stp edged-port

dot1x

dot1x mandatory-domain sensetimeradius

dot1x port-method portbased

#

查看debug信息，截取其中片段可以发现，交换机有发送EAP报文，并且有收到终端的响应：

```
*Aug 19 16:58:09:617 2020 ASCNHZTR-AS-S5130S-29FA-02-IRF DOT1X/7/EVENT: Sending EAP packet: Identifier=2, type=1.
```

```
*Aug 19 16:58:09:618 2020 ASCNHZTR-AS-S5130S-29FA-02-IRF DOT1X/7/PACKET:
```

Transmitted a packet on interface GigabitEthernet1/0/6.

Destination Mac Address=c8f7-503f-f1be

Source Mac Address=743a-208a-f02f

VLAN ID=1

Mac Frame Type=888e

Protocol Version ID=1

Packet Type=0

Packet Length=5.

-----Packet Body-----

Code=1

Identifier=2

Length=5.

```
*Aug 19 16:58:17:134 2020 ASCNHZTR-AS-S5130S-29FA-02-IRF DOT1X/7/PACKET:
```

Received a packet on interface GigabitEthernet1/0/6.

Destination Mac Address=0180-c200-0003

Source Mac Address=c8f7-503f-f1be

Mac Frame Type=888e

Protocol Version ID=1

Packet Type=0

Packet Length=15.
-----Packet Body-----
Code=2
Identifier=2
Length=15.

查看RADIUS交互，发现交换机是有将认证请求报文成功发送至RADIUS服务器的：

```
*Aug 19 16:58:17:173 2020 ASCNHZTR-AS-S5130S-29FA-02-IRF RADIUS/7/PACKET:
  User-Name="zhangyibin"
  NAS-Identifier="ASCNHZTR-AS-S5130S-29FA-02-IRF"
  EAP-Message=0x020200f017a68616e67796962696e
  Message-Authenticator=0x00000000000000000000000000000000
  Framed-MTU=1450
  Framed-Protocol=PPP
  Called-Station-
  NAS-Port-Type=Ethernet
  H3c-Ip-Host-Addr="0.0.0.0 c8:f7:50:3f:f1:be"
  Calling-Station-
  H3C-NAS-Port-Name="GigabitEthernet1/0/6"
  NAS-Port=16801793
  NAS-Port-
  H3c-AVPair="nas:ifindex=6"
  Acct-Session-
  Service-Type=Framed-User
  NAS-IP-Address=10.156.1.5
  H3c-Product-
  H3c-Nas-Startup-Timestamp=1597820936
*Aug 19 16:58:17:175 2020 ASCNHZTR-AS-S5130S-29FA-02-IRF DOT1X/7/EVENT: AAA
processed authentication request: Result=Processing, UserMAC=c8f7-503f-f1be, VLANID=1, In
terface=GigabitEthernet1/0/6.
*Aug 19 16:58:17:175 2020 ASCNHZTR-AS-S5130S-29FA-02-IRF RADIUS/7/EVENT: Sent request
packet successfully.
```

后续设备有成功接收到RADIUS服务器的回应报文：

```
*Aug 19 16:58:17:177 2020 ASCNHZTR-AS-S5130S-29FA-02-IRF RADIUS/7/EVENT: Sent request
packet and create request context successfully.
*Aug 19 16:58:17:177 2020 ASCNHZTR-AS-S5130S-29FA-02-IRF RADIUS/7/EVENT: Added reques
t context to global table successfully.
*Aug 19 16:58:17:177 2020 ASCNHZTR-AS-S5130S-29FA-02-IRF RADIUS/7/EVENT: Processing A
AA request data.
*Aug 19 16:58:17:211 2020 ASCNHZTR-AS-S5130S-29FA-02-IRF RADIUS/7/EVENT: Reply Socket
Fd recieved EPOLLIN event.
*Aug 19 16:58:17:212 2020 ASCNHZTR-AS-S5130S-29FA-02-IRF RADIUS/7/EVENT: Received rep
ly packet succuessfully.
*Aug 19 16:58:17:212 2020 ASCNHZTR-AS-S5130S-29FA-02-IRF RADIUS/7/EVENT: Found reques
t context, dstIP: 10.151.1.248, dstPort: 1812, VPN instance: --(public), socketFd: 77, pktID: 127.
*Aug 19 16:58:17:212 2020 ASCNHZTR-AS-S5130S-29FA-02-IRF RADIUS/7/EVENT: The reply pac
ket is valid.
*Aug 19 16:58:17:213 2020 ASCNHZTR-AS-S5130S-29FA-02-IRF RADIUS/7/EVENT: Decoded repl
y packet successfully.
```

至此，发现debug信息中没有明显的报错信息，结合现场反馈的是认证显示的是通过，但是很快电脑就显示“身份验证失败”无法上网，怀疑跟认证客户端有关，于是让现场使用inode客户端进行802.1X认证来测试。现场测试后反馈，使用inode客户端可以正常进行认证，且终端能一直保持正常上网，因此可以断定非设备配置问题，而是windows自带客户端导致。

解决方法

设备在配置802.1X认证时，会缺省开启在线用户握手功能，开启设备的在线用户握手功能后，设备会定期（时间间隔通过命令dot1x timer handshake-period设置）向通过802.1X认证的在线用户发送握手请求报文（EAP-Request/Identity），以定期检测用户的在线情况。如果设备连续多次（通过命令dot1x retry设置）没有收到客户端的应答报文（EAP-Response/Identity），则会将用户置为下线状态。让现场undo dot1x handshake后，现场反馈使用windows客户端可以正常通过认证且用户不会很快出现下线情况。这是因为部分802.1X客户端不支持与设备进行握手报文的交互，因此建议在这种情况下，关闭设备的在线用户握手功能，避免该类型的在线用户因没有回应握手报文而被强制下线

