

知 The MSR3610-X1 device cannot communicate with the Cisco device over frame relay

Routers 孟普 2020-10-16 Published

Network Topology

NULL

Problem Description

The MSR3610-X1 device cannot communicate with the Cisco device over frame relay. When checking the connectivity, the physical layer of serial port and the protocol layer were up, but the two devices could not communicate with each other.

Process Analysis

1. First, check the interface state. The physical layer and protocol layer states of Serial1/1 port are up

```
[route-Serial1/1]dis ip int br
```

```
*down: administratively down
```

```
(s): spoofing (l): loopback
```

Interface	Physical	Protocol	IP Address	Description
GE0/0	up	up	198.xxx.xx.31	--
GE0/1	*down	down	9.xx.xxx.210	--
GE0/2	down	down	--	--
.....				
Ser1/0	down	down	--	--
Ser1/1	up	up	144.xx.xxx.10	--

2. Secondly, check the interface configuration and the configuration is correct:

```
[route-Serial1/1]dis cur int se 1/1
```

```
#  
interface Serial1/1  
description yinlian  
link-protocol fr  
fr lmi type ansi  
fr map ip 144.xx.xxx.9 101  
#  
fr dlci 101  
broadcast  
ip address 144.xx.xxx.10 255.255.255.252  
#  
return
```

Unable to Ping the address of the peer device

```
[tc_wt-Serial1/1]ping 144.xx.xxx.9
```

```
Ping 144.xx.xxx.9 (144.xx.xxx.9): 56 data bytes, press CTRL_C to break
```

```
Request time out
```

```
Request time out
```

```
.....
```

3. For the problem that the frame relay Link-layer protocol is up but cannot ping each other, we should confirm whether the address mapping configuration of the devices on both ends is correct or whether the route is reachable.

The device configuration is normal and the routing is normal, so these two issues are excluded.

4. Check the interface information and find a large number of error packets and increase in the input direction of interface.

```
Serial1/1  
Current state: UP  
Line protocol state: UP  
Link layer protocol is FR IETF  
LMI DLCI is 0, LMI type is ANSI, frame relay DTE  
LMI status enquiry sent 3, LMI status received 3  
LMI status timeout 0, LMI message discarded 0  
Physical layer: synchronous, Virtual baudrate: 64000 bps  
.....
```

Interface: DTE

Cable type: V35

Clock mode: DTECLK1

Last 300 seconds input rate: 0.00 bytes/sec, 0 bits/sec, 0.00 packets/sec

Last 300 seconds output rate: 0.00 bytes/sec, 0 bits/sec, 0.00 packets/sec

Input:

3 packets, 52 bytes

0 broadcasts, 0 multicasts

5270 errors, 0 runts, 0 giants

0 CRC, 0 align errors, 0 overruns

5270 aborts, 0 no buffers, 0 frame errors

Output:

3 packets, 42 bytes

0 errors, 0 underruns, 0 collisions

0 deferred

In general, if there are many error packets in the input direction, it may be due to a clock problem.

Invert receive-clock: To eliminate the delay of half clock cycle on the circuit, invert the received clock signal of the serial port synchronously on the DTE side.

After this command is configured on all interfaces, it can be up normally and ping each other with the opposite end.

Solution

The problem is resolved after configuration invert receive-clock under the interface.