



# 某局点 S10506X EC单板做堆叠口异常分裂问题

堆叠

柯辉

2022-05-26 发表

## 组网及说明

暂无，两台设备做堆叠

告警信息

暂无

#### 问题描述

现场使用EC类 单板端口做堆叠口，发生异常分裂

过程分析

EC单板做堆叠口，容易出现堆叠口有错包后触发ibod流程，导致跨框流程丢包。当堆叠口收到超小帧，芯片尝试会用ibod动作修复

```
==== display irf cOnfiguration====
MemberID NewID      IRF-Port1      IRF-Port2
1           1        disable          Ten-GigabitEthernet1/2/0/23 Ten-GigabitEther
net1/2/0/24
2           2        Ten-GigabitEthernet2/2/0/23  disable
                  Ten-GigabitEthernet2/2/0/24
```

```
=====display device verbose=====
1/2 LSUM1TGS24EC0 Normal 0 S10500X-7624P12 None
2/2 LSUM1TGS24EC0 Normal 0 S10500X-7624P12 None
```

```
Ten-GigabitEthernet2/2/0/23
Current state: UP
Input: 880 input errors, 878 runts, 0 giants, 0 throttles
      2 CRC, 0 frame, - overruns, 1 aborts
      - ignored, - parity errors
```

```
==== display hardware internal diag hardware-diag-action information chassis 1 slot 6 ====
-----Executed action records:-----
Chassis 1, Slot 2:
1. 2022-04-20, 21:53:20 hot-rebooted by AI.
   reason:SIBOD_ERR. chip 255: the action executed 1 times.
```

## 解决方法

将堆叠口配置在非EC类的接口板上

