

问题描述

现场发现一台主机的eth口自动改变，导致其和集群其他主机之间网络不通。主机原eth口分别为eth2、3、4、5、6、7，改变后的eth口分别为eth3、8、9、10、11、12

```
00:0c:29:14:00:00 scope link
e80:643a:22ff:fedf:744/64 scope link
d-14t forever preferred_lft forever
k-02 ~|# ovs_dbg_listports
-----
NAME   LW  IO  NU  SRIO  MTU  A/L  SPD  MAC                IP      VEN:DEV  DESC      SUBSYS  DRIVE  FIRMWARE
-----
v.0 eth0  1    0    1500  u/d    0  bc:16:95:43:ee:be  0x8086:0x1533 I210      igb       3.25, 0x80000784
v.0 eth1  1    0    1500  u/d    0  bc:16:95:43:ee:bf  0x8086:0x1533 I210      igb       3.25, 0x80000784
v.0 eth9  8    0  0/8  1500  u/u  10000 bc:16:95:42:75:73  0x15b3:0x1015 MT27710 0b44    mlx5_core 14.31.1014 (ZTE0000000)
v.1 eth3  8    0  0/8  1500  u/u  10000 bc:16:95:42:75:74  0x15b3:0x1015 MT27710 0b44    mlx5_core 14.31.1014 (ZTE0000000)
v.0 eth11 8    0  0/8  1500  u/u  10000 bc:16:95:48:56:4d  0x15b3:0x1015 MT27710 0b44    mlx5_core 14.31.1014 (ZTE0000000)
v.1 eth10 8    0  0/8  1500  u/u  10000 bc:16:95:48:56:4e  0x15b3:0x1015 MT27710 0b44    mlx5_core 14.31.1014 (ZTE0000000)
v.0 eth8  8    1  0/8  1500  u/u  10000 bc:16:95:42:74:bd  0x15b3:0x1015 MT27710 0b44    mlx5_core 14.31.1014 (ZTE0000000)
v.1 eth12 8    1  0/8  1500  u/u  10000 bc:16:95:42:74:be  0x15b3:0x1015 MT27710 0b44    mlx5_core 14.31.1014 (ZTE0000000)
-----
Name      MAC                IP      OFPort Vlanx  MTU  VMName  VNC Filter
-----
(v.0)
vswitch0  663a22df0744  10.182.1.12  65534/4  1500
vswitch0_bond
eth7      -1
eth4      -1
ex (v.0)
vs_storage_ex  bc1695427574  10.182.2.12  65534/3  1500
vs_storage_ex_bond  bc1695427574  1/2  1500  17:00.1
eth3      -1
eth5      -1
in (v.0)
vs_storage_in  0a72f9a33a48  10.182.3.12  65534/1  1500
vs_storage_in_bond
eth2      -1
eth6      -1
k-02 ~|#
```

```
02 ~|# ovs_dbg_listports
-----
NAME   LW  IO  NU  SRIO  MTU  A/L  SPD  MAC                IP      VEN:DEV  DESC      SUBSYS  DRIVE  FIRMWARE
-----
v.0 eth0  1    0    1500  u/d    0  bc:16:95:43:ee:be  0x8086:0x1533 I210      igb       3.2
v.0 eth1  1    0    1500  u/d    0  bc:16:95:43:ee:bf  0x8086:0x1533 I210      igb       3.2
v.0 eth9  8    0  0/8  1500  u/u  10000 bc:16:95:42:75:73  0x15b3:0x1015 MT27710 0b44    mlx5_core 14.
v.1 eth3  8    0  0/8  1500  u/u  10000 bc:16:95:42:75:74  0x15b3:0x1015 MT27710 0b44    mlx5_core 14.
v.0 eth11 8    0  0/8  1500  u/u  10000 bc:16:95:48:56:4d  0x15b3:0x1015 MT27710 0b44    mlx5_core 14.
v.1 eth10 8    0  0/8  1500  u/u  10000 bc:16:95:48:56:4e  0x15b3:0x1015 MT27710 0b44    mlx5_core 14.
v.0 eth8  8    1  0/8  1500  u/u  10000 bc:16:95:42:74:bd  0x15b3:0x1015 MT27710 0b44    mlx5_core 14.
v.1 eth12 8    1  0/8  1500  u/u  10000 bc:16:95:42:74:be  0x15b3:0x1015 MT27710 0b44    mlx5_core 14.
-----
Name      MAC                IP      OFPort Vlanx  MTU  VMName  VNC Filter
-----
(v.0)
vswitch0  bc169548564d  10.182.1.12  65534/4  1500
vswitch0_bond  slb, lacp=n,
eth11     bc169548564d  1/7  *uxe 1500  31:00.0
eth12     bc16954274be  2/8  uxe 1500  98:00.1
ex (v.0)
vs_storage_ex  bc169548564e  10.182.2.12  65534/3  1500
vs_storage_ex_bond  slb, lacp=n, fallab
eth3      bc1695427574  4/2  *uxe 1500  17:00.1
eth10     bc169548564e  5/9  *uxe 1500  31:00.1
in (v.0)
vs_storage_in  bc16954274bd  10.182.3.12  65534/1  1500
vs_storage_in_bond  slb, lacp=n,
eth9      bc1695427573  1/5  *uxe 1500  17:00.0
eth8      bc16954274bd  2/6  uxe 1500  98:00.0
02 ~|#
```

过程分析

1、查看/var/log/openvswitch/ovs-vswitchd.log日志，可以看到现场最开始报原eth2口查询异常是在3月15日23:24左右。

```
Mar 15 23:24:44|00021|ofproto_dpif|INFO|system@ovs-system: Datapath supports ct_orig_tuple
Mar 15 23:24:44|00022|ofproto_dpif|INFO|system@ovs-system: Datapath supports ct_orig_tuple6
Mar 15 23:24:44|00023|bridge|INFO|bridge vs_storage_in: added interface vs_storage_in on port 65534
Mar 15 23:24:44|00024|bridge|WARN|could not open network device eth2 (No such device)
Mar 15 23:24:44|00025|bridge|WARN|could not open network device eth6 (No such device)
Mar 15 23:24:44|00026|bridge|INFO|bridge vs_storage_ex: added interface eth3 on port 1
Mar 15 23:24:44|00027|bridge|WARN|could not open network device eth5 (No such device)
Mar 15 23:24:44|00028|bridge|INFO|bridge vs_storage_ex: added interface
```

2、通过last reboot查询主机历史重启记录，可以看到在3月15日23:24左右发生过重启，怀疑是当时主机重启导致的eth口改变。

```
last reboot
-----
reboot   system boot  4.14.131-generic Fri Mar 24 15:59 - 18:53 (02:54)
reboot   system boot  4.14.131-generic Thu Mar 16 15:06 - 18:53 (8+03:47)
reboot   system boot  4.14.131-generic Thu Mar 16 01:20 - 18:53 (8+17:32)
reboot   system boot  4.14.131-generic Wed Mar 15 23:24 - 18:53 (8+19:28)
reboot   system boot  4.14.131-generic Wed Aug 17 12:40 - 18:53 (219+06:12)
```

3、进一步查看该主机/etc/sysconfig/network-scripts目录下各eth网络配置文件的最新修改时间，可以看到eth8、9等eth文件确实是在主机重启时间点新生成。

```
[root@QDCVK-02 network-scripts]# ll
total 304
-rw-r--r-- 1 root root 236 Aug 17 2022 ifcfg-eth0
-rw-r--r-- 1 root root 236 Aug 17 2022 ifcfg-eth1
-rw-r--r-- 1 root root 254 Mar 15 23:24 ifcfg-eth10
-rw-r--r-- 1 root root 254 Mar 15 23:24 ifcfg-eth11
-rw-r--r-- 1 root root 254 Mar 15 23:24 ifcfg-eth12
-rw-r--r-- 1 root root 261 Dec 16 16:39 ifcfg-eth2
-rw-r--r-- 1 root root 238 Dec 16 16:39 ifcfg-eth3
-rw-r--r-- 1 root root 260 Dec 16 16:43 ifcfg-eth4
-rw-r--r-- 1 root root 261 Dec 16 16:44 ifcfg-eth5
-rw-r--r-- 1 root root 261 Dec 16 16:45 ifcfg-eth6
-rw-r--r-- 1 root root 260 Dec 16 16:46 ifcfg-eth7
-rw-r--r-- 1 root root 252 Mar 15 23:24 ifcfg-eth8
-rw-r--r-- 1 root root 252 Mar 15 23:24 ifcfg-eth9
-rw-r--r-- 1 root root 254 Aug 24 2018 ifcfg-lo
-rw-r--r-- 1 root root 203 Aug 17 2022 ifcfg-vs_storage_ex
-rw-r--r-- 1 root root 203 Aug 17 2022 ifcfg-vs_storage_in
-rw-r--r-- 1 root root 364 Aug 17 2022 ifcfg-vswitch0
lrwxrwxrwx 1 root root 24 Aug 17 2022 bin/ifdown
```

4、对比前后eth口变化，发现存在原eth3口未改变，怀疑其ifcfg-eth配置文件和其他eth口不一样。对比后可看到，相较eth2、4、5、6、7，其ifcfg-eth配置文件中无"ethtool -G ethx rx 4096"参数，怀疑是该参数导致的现场eth口改变。

```
[root@QDCVK-03 network-scripts]# cat -A ifcfg-eth3
NAME="eth3"$
DEVICE="eth3"$
HWADDR="bc:16:95:42:75:ec"$
TYPE="Ethernet"$
NOZEROCONF="no"$
ONBOOT="yes"$
HOTPLUG="yes"$
NM_CONTROLLED="no"$
IPV6_AUTOCONF="no"$
# generated by ovs frist_boot.sh$
IPV6INIT="no"$
DEFROUTE="yes"$
IPV4_FAILURE_FATAL="yes"3$
```

```
[root@QDCVK-03 network-scripts]# cat -A ifcfg-eth2
NAME="eth2"$
DEVICE="eth2"$
HWADDR="bc:16:95:42:75:eb"$
TYPE="Ethernet"$
NOZEROCONF="no"$
ONBOOT="yes"$
HOTPLUG="yes"$
NM_CONTROLLED="no"$
IPV6_AUTOCONF="no"$
# generated by ovs frist_boot.sh$
IPV6INIT="no"$
DEFROUTE="yes"$
IPV4_FAILURE_FATAL="yes"$
ethtool -G eth2 rx 4096$
[root@QDCVK-03 network-scripts]# stat ifcfg-eth2
```

5、经确认，“ethtool -G ethx rx 4096”参数为现场手动添加，而Workspace主机系统禁止修改默认的ifcfg-eth网络配置文件参数。一旦ifcfg-eth文件内参数被改变，主机在重启时通过ovs读取文件内格式不一致，就会重新生成eth口。

