

知 某局点t1000下联组播业务异常问题


域间策略/安全域 ASPF 攻击防范 陈泽勇 2024-05-29 发表

组网及说明

t1000透明部署串联在核心交换机和防火墙之间，上下联都做的二层聚合。

问题描述

没有接入t1000设备的时候，组播业务正常；接入之后组播业务卡顿且花屏如下（为了方便测试该组播接收者直连在t1000 1/0/10口下）：



跳过设备直连核心交换机回显如下：




过程分析

1、没有接入t1000设备的时候，组播业务正常；接入之后组播业务卡顿且花屏如下：



2、查看配置安全策略全放通且没有开启dpi，查看cpu和内存都是正常的没有异常信息：



```
#
security-policy ip
rule 0 name any
action pass
#
```

```
=====display memory=====
Memory statistics are measured in KB:
Slot 1:
Mem:          Total    Used    Free    Shared  Buffers  Cached  FreeRatio
-/+ Buffers/Cache: 2420416 5790336
```

Mem:	Total	Used	Free	Shared	Buffers	Cached	FreeRatio
	8210752	3027520	5183232	0	20160	586944	64.4%

3. 后续将接电脑的接口的flow-intre改为5, 查看display interface发现可能存在突发流量, 敲了几次有一次达到了40%左右, 其余都是1%左右。

一次40%:

```
[H3C_XY_IPS]dis interface gi1/0/10
GigabitEthernet1/0/10
Current state: UP
Line protocol state: UP
IP packet frame type: Ethernet II, hardware address: 58b3-8fce-c4ac
Description: GigabitEthernet1/0/10 Interface
Bandwidth: 1000000 kbps
Loopback is not set
Media type is twisted pair, loopback not set, promiscuous mode set
1000Mb/s, Full-duplex, link type is autonegotiation
Output flow-control is disabled, input flow-control is disabled
1000Mbps-speed mode, full-duplex mode
Link speed type is autonegotiation, link duplex type is autonegotiation
Flow-control is not enabled
Maximum frame length: 9216
Allow jumbo frames to pass
Broadcast max-ratio: 100%
Multicast max-ratio: 100%
Unicast max-ratio: 100%
PVID: 100
MDI type: Automdix
Port link-type: Access
Tagged VLANs: None
Untagged VLANs: 100
Last link flapping: 1 hours 6 minutes 7 seconds
Last clearing of counters: Never
Current system time:2024-05-28 14:30:59
Last time when physical state changed to up:2024-05-28 13:24:52
Last time when physical state changed to down:2024-05-28 11:42:09
Peak input rate: 31315 bytes/sec, at 2024-05-28 11:34:13
Peak output rate: 2010447 bytes/sec, at 2024-05-28 14:11:03
Last 5 second input: 3 packets/sec 620 bytes/sec 0%
Last 5 second output: 39813 packets/sec 48659085 bytes/sec 40%
Input (total): 17071 packets, 2531663 bytes
12039 unicasts, 1133 broadcasts, 3899 multicasts, 0 pauses
Input (normal): 17071 packets, 2531663 bytes
12039 unicasts, 1133 broadcasts, 3899 multicasts, 0 pauses
Input: 0 input errors, 0 runts, 0 giants, - throttles
0 CRC, 0 frame, 0 overruns, 0 aborts
0 ignored, - parity errors
Output (total): 8503557 packets, 10392435976 bytes
16055 unicasts, 5841 broadcasts, 8481661 multicasts, 0 pauses
Output (normal): 8503557 packets, 10392435976 bytes
16055 unicasts, 5841 broadcasts, 8481661 multicasts, 0 pauses
Output: 0 output errors, 0 underruns, - buffer failures
0 aborts, 0 deferred, 0 collisions, 0 late collisions
```

其余几次都只有1%:

```
[H3C_XY_IPS]dis interface g1/0/10
GigabitEthernet1/0/10
Current state: UP
Line protocol state: UP
IP packet frame type: Ethernet II, hardware address: 58b3-8fce-c4ac
Description: GigabitEthernet1/0/10 Interface
Bandwidth: 1000000 kbps
Loopback is not set
Media type is twisted pair, loopback not set, promiscuous mode set
1000Mb/s, Full-duplex, link type is autonegotiation
Output flow-control is disabled, input flow-control is disabled
100Mbps-speed mode, full-duplex mode
Link speed type is autonegotiation, link duplex type is autonegotiation
Flow-control is not enabled
Maximum frame length: 9216
Allow jumbo frames to pass
Broadcast max-ratio: 1000
Multicast max-ratio: 1000
Unicast max-ratio: 1000
PVID: 100
MDI type: Automdix
Port link-type: Access
Tagged VLANs: None
Untagged VLANs: 100
Last link flapping: 1 hours 6 minutes 19 seconds
Last clearing of counters: Never
Current system time: 2024-05-28 14:31:11
Last time when physical state changed to up: 2024-05-28 13:24:52
Last time when physical state changed to down: 2024-05-28 11:42:09
Peak input rate: 31315 bytes/sec, at 2024-05-28 11:34:13
Peak output rate: 2010447 bytes/sec, at 2024-05-28 14:11:03
Last 5 second input: 0 packets/sec 0 bytes/sec 0%
Last 5 second output: 1356 packets/sec 1651393 bytes/sec 1%
```

4、后续display packet dorp interface去看丢包情况发现是没有记录的都是空，且开启burst-mode enable之后故障依旧：

```
packets dropped due to create mbuf: 0
GigabitEthernet1/0/10:
Packets dropped due to runt frame: 0
Packets dropped due to packet too long: 0
Packets dropped due to align: 0
Packets dropped due to under run: 0
Packets dropped due to over run: 0
Packets dropped due to CRC: 0
Packets dropped due to no buffer: 0
Packets dropped due to dribbles: 0
Packets dropped due to lost carriers: 0
Packets dropped due to tx collision: 0
Packets dropped due to deferred: 0
Packets dropped due to MAC filter: 0
Packets dropped due to cpu receive: 0
Packets dropped due to create mbuf: 0
GigabitEthernet1/0/11:
Packets dropped due to runt frame: 0
Packets dropped due to packet too long: 0
```

5、让现场直接跳过t1000接上联的核心交换机发现监控画面恢复正常，于是在终端侧异常和正常的时候都抓了对应的报文发现异常时候的报文是每一份丢失7-8个tc帧，还是丢在t1000上了。

正常抓包：

128	0.336144	30.12.4.5	238.12.4.5	MPG TS	1356 [MP2I fragment of a reassembled packet]
127	0.336144	30.12.4.5	238.12.4.5	MPG TS	1356 [MP2I fragment of a reassembled packet]
128	0.336144	30.12.4.5	238.12.4.5	MPG TS	1356 [MP2I fragment of a reassembled packet]
129	0.336144	30.12.4.5	238.12.4.5	MPG TS	1376 [MP2I fragment of a reassembled packet]
130	0.345097	30.12.4.5	238.12.4.5	MPG	418 10000 + 20000 Len=376
131	0.359667	30.12.4.5	238.12.4.5	MPG TS	418 10000 + 20000 Len=376
132	0.375579	30.12.4.5	238.12.4.5	MPG TS	1356 video-stream [MP2I fragment of a reassembled packet]
133	0.375579	30.12.4.5	238.12.4.5	MPG TS	1356 [MP2I fragment of a reassembled packet]
134	0.375579	30.12.4.5	238.12.4.5	MPG TS	1356 [MP2I fragment of a reassembled packet]
135	0.375579	30.12.4.5	238.12.4.5	MPG TS	1356 [MP2I fragment of a reassembled packet]
136	0.375579	30.12.4.5	238.12.4.5	MPG TS	1356 [MP2I fragment of a reassembled packet]
137	0.375579	30.12.4.5	238.12.4.5	MPG TS	1356 [MP2I fragment of a reassembled packet]

异常抓包：

29	0.000328	30.12.72.34	238.12.72.34	MPG TS	238 [MP2I fragment of a reassembled packet]
30	0.000328	30.12.72.34	238.12.72.34	MPG TS	1356 [MP2I fragment of a reassembled packet]
31	0.006300	30.12.0.15	238.12.0.15	MPG	418 10000 + 20000 Len=376
32	0.015300	30.12.4.5	238.12.4.5	MPG	418 10000 + 20000 Len=376
33	0.017136	30.12.72.34	238.12.72.34	MPG	418 10000 + 20000 Len=376
34	0.025694	30.12.0.15	238.12.0.15	MPG	606 10000 + 20000 Len=564
35	0.035956	30.12.4.5	238.12.4.5	MPG TS	1356 [MP2I fragment of a reassembled packet]
36	0.035956	30.12.4.5	238.12.4.5	MPG TS	1356 video-stream [MP2I fragment of a reassembled packet]
37	0.035956	30.12.4.5	238.12.4.5	MPG TS	1356 [MP2I fragment of a reassembled packet]
38	0.035956	30.12.4.5	238.12.4.5	MPG TS	1356 [MP2I fragment of a reassembled packet]
39	0.035956	30.12.4.5	238.12.4.5	MPG TS	1356 [MP2I fragment of a reassembled packet]
40	0.035956	30.12.4.5	238.12.4.5	MPG TS	1356 [MP2I fragment of a reassembled packet]
41	0.036090	30.12.4.5	238.12.4.5	MPG TS	1356 [MP2I fragment of a reassembled packet]
42	0.036090	30.12.4.5	238.12.4.5	MPG TS	1356 [MP2I fragment of a reassembled packet]

解决方法

后续和产线确认，目前版本都是组播逐包转发，可能会引入乱序。后续关闭组播逐包后测试正常。
probe

```
undo hardware cavium-chip mcast-per-packet enable
```