


S10500交换机OSPF Router ID冲突问题排查案例

一、组网：



两台S10500做IRF，分别插一块IPS、FW插卡，作为核心设备采用OSPF与网络内其他设备交互路由协议。

二、问题描述：

S10500的设备上不断打印类似于下面的信息：

*Jun 19 14:25:58:436 2012 S10508 RM/6/RMDEBUG:

OSPF 10 :OSPF received packet having **conflicted Router ID :10.255.0.1** from interface Vlan-interface806.

#Jun 18 15:14:35:495 2012 S10508 OSPF/4/IF_BAD_RX: OSPF TrapID1.3.6.1.2.1 .14.16.2.8: **Non-virtual Interface 10.254.0.41 index 0 Router 10.255.0.1 received error packet from 10.254.0.41 PacketType 1.**

#Jun 18 15:14:35:495 2012 S10508 OSPF/4/IF_BAD_RX: OSPF TrapID1.3.6.1.2.1 .14.16.2.8: **Non-virtual Interface 10.254.0.57 index 0 Router 10.255.0.1 received error packet from 10.254.0.57 PacketType 1.**

#Jun 18 15:14:35:496 2012 S10508 OSPF/4/IF_BAD_RX: OSPF TrapID1.3.6.1.2.1 .14.16.2.8: **Non-virtual Interface 10.254.0.73 index 0 Router 10.255.0.1 received error packet from 10.254.0.73 PacketType 1.**

三、过程分析：

从打印的信息来看，故障现象比较明显，网络内存在Router ID冲突，冲突的Router ID就是S10500的Router ID 10.255.0.1。

通过display ospf error 也可以清楚的看到OSPF Router ID confusion错误在不断增长。

display ospf error

OSPF Process 10 with Router ID 10.255.0.1

OSPF Packet Error Statistics

576978 : OSPF Router ID confusion 0: OSPF bad packet

0 : OSPF bad version 0: OSPF bad checksum

0 : OSPF bad area ID 0: OSPF drop on unnumbered interface

0 : OSPF bad virtual link 0: OSPF bad authentication type

0 : OSPF bad authentication key 0: OSPF packet too small

0 : OSPF Neighbor state low 0: OSPF transmit error

0 : OSPF interface down 2: OSPF unknown neighbor

0 : HELLO: Netmask mismatch 0: HELLO: Hello timer mismatch

0 : HELLO: Dead timer mismatch 0: HELLO: Extern option mismatch

0 : HELLO: Neighbor unknown 0: DD: MTU option mismatch

0 : DD: Unknown LSA type 0: DD: Extern option mismatch

```
0 : LS ACK: Bad ack      0: LS ACK: Unknown LSA type
0 : LS REQ: Empty request 0: LS REQ: Bad request
0 : LS UPD: LSA checksum bad 0: LS UPD: Received less recent LSA
0 : LS UPD: Unknown LSA type
```

display ospf error

OSPF Process 10 with Router ID 10.255.0.1

OSPF Packet Error Statistics

```
576994 : OSPF Router ID confusion  0: OSPF bad packet
0 : OSPF bad version      0: OSPF bad checksum
0 : OSPF bad area ID      0: OSPF drop on unnumbered interface
0 : OSPF bad virtual link  0: OSPF bad authentication type
0 : OSPF bad authentication key 0: OSPF packet too small
0 : OSPF Neighbor state low  0: OSPF transmit error
0 : OSPF interface down     0: OSPF unknown neighbor
0 : HELLO: Netmask mismatch  0 : HELLO: Hello timer mismatch
0 : HELLO: Dead timer mismatch 0: HELLO: Extern option mismatch
0 : HELLO: Neighbor unknown  0: DD: MTU option mismatch
0 : DD: Unknown LSA type    0: DD: Extern option mismatch
0 : LS ACK: Bad ack      0: LS ACK: Unknown LSA type
0 : LS REQ: Empty request 0 : LS REQ: Bad request
0 : LS UPD: LSA checksum bad 0: LS UPD: Received less recent LSA
0 : LS UPD: Unknown LSA type
```

且现场S10500设备上每一个VLAN虚接口都提示收到了错包。

现场组网中OSPF设备较多，逐一排查比较困难，要找到哪台设备和S10500的Router ID冲突了就存在一个很大的困难，问题的焦点就集中在如何找出这台冲突的设备。这里介绍一个相对简单的方法，在S10500上配置一个ACL来匹配OSPF报文。

```
acl number 3333
```

```
rule permit ip ospf
```

然后设备上开启debug引用此ACL，这样就可以只打印OSPF相关的协议报文：debug ip packet acl 3333

打开debug开关之后，发现了下面的debug信息：

```
*Jun 19 14:25:58:433 2012 S10508 IPTRAP/7/debug_case:
```

```
Delivering, interface = Vlan-interface806, version = 4, headlen = 20, tos = 192,
pktlen = 68, pktid = 26772, offset = 0, ttl = 1, protocol = 89,
```

```
checksum = 25785, s = 10.254.0.81, d = 224.0.0.5
```

```
prompt: IP packet is delivering up!
```

```
*Jun 19 14:25:58:433 2012 S10508 IPFWD/7/debug_case: -Chassis=2-Slot=7;
```

```
Receiving, interface = Vlan-interface806, version = 4, headlen = 20, tos = 192,
pktlen = 68, pktid = 26772, offset = 0, ttl = 1, protocol = 89,
```

```
checksum = 25785, s = 10.254.0.81, d = 224.0.0.5
```

```
prompt: Receiving IP packet
```

从debug信息，我们发现，设备从VLAN interface 806发出去一个OSPF报文，紧接着报文又从这个VLAN interface 806收到，收到报文的源IP10.254.0.81恰好就是S10500设备自己的VLAN 806虚接口地址。这样就报了router ID 冲突以及收到错包的提示。

接下来的疑问就是为何设备会从这个虚接口收到自己发送的OSPF报文呢？通过查看配置，我们发现S10500上报此错误是因为IPS将OSPF组播报文弹回导致，OSPF报文为何会被弹回呢？我们想到此设备上配置了IPS插卡，检查IPS插卡配置发现，原来是S10500上插卡的接口Ten-GigabitEthernet1/7/0/1和Ten-GigabitEthernet2/7/0/1的配置存在问题，导致IPS插卡 deny广播、组播、arp的策略没有生效导致，下面是错误的

配置。红色部分错误配置导致设备实际上并没有deny掉ACL 4000中定义的报文。

```
acl number 4000
description Match-MultiCast-Broadcast-ARP
rule 0 permit dest-mac 0100-0000-0000 ff00-0000-0000
rule 5 permit dest-mac ffff-ffff-ffff ffff-ffff-ffff
rule 10 permit type 0806 ffff
#
traffic classifier Multicast-Broadcast-ARP operator or
if-match acl 4000
#
traffic behavior Deny-Multicast-Broadcast-ARP
filter deny
qos policy Deny-Multicast-Broadcast-ARP
classifier Multicast-Broadcast-ARP behavior Deny-Multicast-Broadcast-ARP
#
interface Ten-GigabitEthernet1/7/0/1
port link-mode bridge
description Link_To_IPS-01
port link-type trunk
undo port trunk permit vlan 1
port trunk permit vlan 800 802 805 807 809 to 810
flow-interval 5
stp disable
packet-filter 4000 inbound
qos apply policy Deny-Multicast-Broadcast-ARP inbound
mac-address mac-learning disable
#
interface Ten-GigabitEthernet2/7/0/1
port link-mode bridge
description Link_To_IPS-02
port link-type trunk
undo port trunk permit vlan 1
port trunk permit vlan 801 803 806 808 to 810
flow-interval 5
stp disable
packet-filter 4000 inbound
qos apply policy Deny-Multicast-Broadcast-ARP inbound
mac-address mac-learning disable
```

四、 解决方法：

问题原因清楚了之后。只有修改配置将ACL 4000中定义的报文deny掉即可。修改后的配置如下：

```
interface Ten-GigabitEthernet1/7/0/1
port link-mode bridge
description Link_To_IPS-01
port link-type trunk
undo port trunk permit vlan 1
port trunk permit vlan 800 802 805 807 809 to 810
```

```
flow-interval 5

stp disable

qos apply policy Deny-Multicast-Broadcast-ARP outbound

mac-address mac-learning disable

interface Ten-GigabitEthernet2/7/0/1

port link-mode bridge

description Link_To_IPS-02

port link-type trunk

undo port trunk permit vlan 1

port trunk permit vlan 801 803 806 808 to 810

flow-interval 5

stp disable

qos apply policy Deny-Multicast-Broadcast-ARP outbound

mac-address mac-learning disable
```

修改配置之后不再报此OSPF Router ID冲突错误。

这个案例重点在于三点：

1. 这个OSPF Router ID冲突故障相对比较少见，在配置IPS插卡时，一定要注意deny掉组播、arp、广播等报文防止其被环回。
2. 在排查OSPF Router ID冲突的问题时，大家可以使用ACL来匹配OSPF报文，开启debug ip packet时引用此ACL，这样可以只debug到OSPF报文，并且可以看到报文的源IP，就不需要逐台设备检查配置去排查冲突源了。
3. 下发策略时需要在S10500与IPS插卡的outbound方向下发，如果在inbound方向下发只能deny掉部分报文，因为协议报文会被系统ACL抓上CPU，因此inbound方向下发时不能deny掉OSPF这样的协议报文。

```
qos apply policy Deny-Multicast-Broadcast-ARP outbound
```