

The S6850 IRF cannot be established, and the device prompts that the IRF port cannot receive packets

Switches 龚训杰 2021-05-19 Published

Null

## Problem Description

The device IRF cannot be established, and the device prompts that the IRF port cannot receive packe ts

## Process Analysis

Check whether the following configurations of the two devices in the IRF are the same:

- 1.display hardware-resource vxlan
- 2.display system-working-mode
- 3.display hardware-resource switch-mode
- 4.display hardware-resource routing-mode

## Solution

- 1.hardware-resource vxlan xxx
- 2.system-working-mode xxx
- 3.hardware-resource switch-mode xxx
- 4.hardware-resource routing-mode xxx