

知 The S6850 IRF cannot be established, and the device prompts that the IRF port cannot receive packets

Switches 龚训杰 2021-05-19 Published

Network Topology

Null

Problem Description

The device IRF cannot be established, and the device prompts that the IRF port cannot receive packets

Process Analysis

Check whether the following configurations of the two devices in the IRF are the same:

- 1.display hardware-resource vxlan
- 2.display system-working-mode
- 3.display hardware-resource switch-mode
- 4.display hardware-resource routing-mode

Solution

- 1.hardware-resource vxlan xxx
- 2.system-working-mode xxx
- 3.hardware-resource switch-mode xxx
- 4.hardware-resource routing-mode xxx

