

知 WX2540H扩容License在设备上激活文件失败问题处理

License

何信 2017-03-21 发表

给WX2540H扩容License，在设备上激活文件失败。

激活文件时提示如下信息：

```
[WX2540_2]license activation-file install flash:/210235A1JMC15A0000592017012010522084428.ak
This operation might take some time. Do not perform any other operations until the operation is
completed or a failure message is displayed. Please wait...
The activation file cannot be parsed now.
```

核对现场导入的License文件2594字节无误，确认文件本身没有问题。

```
<WX2540_2>dir
```

Directory of flash:

```
0 -rw- 2594 Jan 20 2017 12:27:27 210235A1JMC15A0000592017012010522084428.ak
```

查看License信息发现设备上已注册3个16步长的License。

```
[WX2540_2]dis license
```

```
flash:/license/attachmentname03
```

Feature: APMGR

Product Description: Enhanced Access Controller License,16 APs,for Verticals,for V7

Registered at: 2016-01-16 18:25:00

License Type: Permanent

Current State: In use

```
flash:/license/attachmentname02
```

Feature: APMGR

Product Description: Enhanced Access Controller License,16 APs,for Verticals,for V7

Registered at: 2016-01-16 18:24:54

License Type: Permanent

Current State: In use

```
flash:/license/attachmentname
```

Feature: APMGR

Product Description: Enhanced Access Controller License,16 APs,for Verticals,for V7

Registered at: 2016-01-16 18:24:48

License Type: Permanent

Current State: In use

WX2540H最大支持AP数48，步长16的License最多注册3个，现场已注册3个，因此不能再注册。