

知 某局点WX3540X 云简平台固定账号登录失败


绿洲平台 王姑娘 2022-03-12 发表

组网及说明

AC+Fit AP 跨公网组网， AC已注册到云简平台， cmcc做的本地转发。AC版本ESS 1046P01。

问题描述

现场按照官网的云简平台认证手册实施开局，配置大部分都是云简平台下发的。做的固定账号认证，目前可以弹出认证界面但是无法认证成功，输入账号和密码后登录，提示登录失败。



过程分析

1、收集诊断后先查看了配置，与官网云简平台认证手册固定账号认证配置对比后，并没有发现有什么问题。

```
#  
wlan service-template 5  
description ceshi  
ssid ceshi  
vlan 255  
client forwarding-location ap  
portal enable method direct  
portal domain cloud  
portal apply web-server 5  
portal temp-pass period 20 enable  
service-template enable  
#  
domain name cloud  
authorization-attribute idle-cut 30  
authorization-attribute session-timeout 360  
authentication portal none  
authorization portal none  
accounting portal none  
#  
portal host-check enable  
portal client-gateway interface Vlan-interface1  
portal free-rule 2346257224 destination open.weixin.qq.com  
portal free-rule 2346257225 destination ip any tcp 5223  
portal free-rule 2346257226 destination ip 114.114.114.114 255.255.255.255  
portal free-rule 2346257227 destination ip any udp 53  
portal free-rule 2346257228 destination ip any tcp 53  
portal free-rule 2346257229 destination oasisauth.h3c.com  
portal free-rule 2346257230 destination short.weixin.qq.com  
portal free-rule 2346257231 destination mp.weixin.qq.com  
portal free-rule 2346257232 destination long.weixin.qq.com  
portal free-rule 2346257233 destination dns.weixin.qq.com  
portal free-rule 2346257234 destination minorshort.weixin.qq.com  
portal free-rule 2346257235 destination extshort.weixin.qq.com  
portal free-rule 2346257236 destination szshort.weixin.qq.com  
portal free-rule 2346257237 destination szlong.weixin.qq.com  
portal free-rule 2346257238 destination szextshort.weixin.qq.com  
portal free-rule 2346257239 destination isdspeed.qq.com  
portal free-rule 2346257240 destination wx.qlogo.cn  
portal free-rule 2346257241 destination long.open.weixin.qq.com  
portal free-rule 2346257242 destination res.wx.qq.com  
portal free-rule 2346257243 destination wifi.weixin.qq.com  
portal safe-redirect enable  
portal safe-redirect user-agent Android  
portal safe-redirect user-agent CaptiveNetworkSupport  
portal safe-redirect user-agent MicroMessenger  
portal safe-redirect user-agent Mozilla  
portal safe-redirect user-agent WeChat  
portal safe-redirect user-agent micromessenger  
#  
portal web-server 5  
url http://oasisauth.h3c.com/portal/protocol  
server-type oauth  
url-parameter template_id value 586627  
if-match user-agent CaptiveNetworkSupport redirect-url http://oasisauth.h3c.com/generate_404  
if-match user-agent Dalvik/2.1.0(Linux;U;Android7.0;HUAWEI redirect-url  
http://oasisauth.h3c.com/generate_404  
if-match original-url http://10.168.168.168 temp-pass  
if-match original-url http://captive.apple.com user-agent Mozilla temp-pass redirect-url http://oasisaut
```

```

h.h3c.com/portal/protocol
if-match original-url http://o2o.gting.com/wifi/echo temp-pass redirect-url http://oasisauth.h3c.com/ge
解决方法
在原有AC的配置基础上http://www.apple.com指定域名对应的正确IP地址重写AC后问题解决。
#http://oasisauth.h3c.com/portal/protocol
dns server 119.X.X.X
ip host local-web-server comp 101.36.161.146 //增加相关配置
#
portal local-web-server https
#
ip http enable
ip https port 8668
ip https enable
#
portal mac-trigger-server cloud
binding-retry 2 interval 3
cloud-binding enable
2、查看云简平台认证手册中，AP跨公网注册解决方案有两种，有“配置CMCC方案”与“修改HTTP服务端口方案”。默认情况下，设备侧提供HTTP服务的端口为80端口，终端进行云认证时需通过此端口与设备进行交互。若运营方的网络为AP跨公网注册至AC或路由器，AP本地转发终端数据流量，且运营方无法为AC或路由器设备申请对外提供服务的80端口时，需对AC或路由器设备以及网络中其它相关设备进行额外配置。
看配置中选择的是方案一。
#
portal server cloud
ip 101.36.161.146
server-type cmcc
server-register interval 60
让现场按照如下修改了方案，如下：
#
portal web-server cloud
url http://oasisauth.h3c.com/portal/protocol?
redirect_uri=http://182.XXX.XXX.XXX:8088/portal/cloudlogin.html
#
ip http port 8088
#
portal local-web-server http
tcp-port 8088
但测试后故障依旧
3、检查AC 本地与云简网络互联的TCP连接信息，发现异常：
[3540X] display tcp verbose | b portal
.....
Creator: portald[5679]
State: ISCONNECTED
Options: SO_SEQPACKET
Error: 0
Receiving buffer(cc/hiwat/lowat/drop/state): 14105114 / 130560 / 1 / 0 / N/A
Sending buffer(cc/hiwat/lowat/state): 4273052596 / 131070 / 512 / N/A
Type: 1
Protocol: 6
Inpcb flags: INP_ANONPORT INP_SYNCPCB
Inpcb extflag: N/A
Inpcb vflag: INP_IPV4
TTL: 255(minimum TTL: 0)
Connection state: ESTABLISHED
TCP options: TF_NODELAY TF_REQ_SCALE TF_RCVD_SCALE TF_REQ_TSTMP TF_SACK_PER
MIT
NSR state: CLOSED(M)
Send VRF: 0x0
Receive VRF: 0x0 Connection info: Src =101.202.6.3:16270, Dst = 101.36.161.143:443 //AC 与错
误的云简网络IP和端口建立了连接
通过上述查看，已找到故障的原因。AC与错误的云简网络IP和端口建立了连接。目前正确的云简网络I
P地址端口应该为：101.36.161.146:80。

```

