

知 6520X-EI 提示: The airflow direction of The two Power Fan is Different

电源 风扇 罗书鹏 2023-09-05 发表

组网及说明

不涉及

告警信息

```
%Jan 1 08:40:41:980 2021 [REDACTED] DRVPLAT/4/DrvDebug: -Slot=2;
ALARM:The airflow direction of The two Power Fan is Different on slot 2 ,please check it.
%Jan 1 08:40:50:003 2021 [REDACTED] DRVPLAT/4/DrvDebug:
ALARM:The airflow direction of The two Power Fan is Different on slot 1 ,please check it.
%Jan 1 08:41:42:027 2021 [REDACTED] DRVPLAT/4/DrvDebug: -Slot=2;
ALARM:The airflow direction of The two Power Fan is Different on slot 2 ,please check it.
%Jan 1 08:41:50:015 2021 [REDACTED] DRVPLAT/4/DrvDebug:
ALARM:The airflow direction of The two Power Fan is Different on slot 1 ,please check it.
%Jan 1 08:42:42:029 2021 [REDACTED] DRVPLAT/4/DrvDebug: -Slot=
2:
ALARM:The airflow direction of The two Power Fan is Different
on slot 2 ,please check it.
%Jan 1 08:42:50:018 2021 [REDACTED] DRVPLAT/4/DrvDebug:
ALARM:The airflow direction of The two Power Fan is Different
on slot 1 ,please check it.
%Jan 1 08:43:42:028 2021 [REDACTED] DRVPLAT/4/DrvDebug: -Slot=
2;
```



问题描述

两台6520X做堆叠, 提示日志: The airflow direction of The two Power Fan is Different on slot 1 ,please check it

过程分析

首先查看日志分析The airflow direction of The two Power Fan is Different on slot 1 ,please check it
这个打印是电源的风扇风向问题，配置fan prefer-direction调整的是设备风扇风向，是设备插入的两个电源风扇风向不一致出现的提示。现场电源模块不一样，建议用一样的电源模块。

解决方法

修改相同的电源模块之后，告警消失，故障恢复。

