

问题描述

在全局下批量升级和在接口下升级ONU都失败

update onu type ET908-H-POE-W protocol-type ctc filename flash:/ET908HPOEW105.app
[S7506X-Olt1/1/0/7]update onu protocol-type ctc filename ET908HPOEW105.app

```

[SSPZX_S7506X-Olt1/1/0/7:1]display epon onu-update interface Olt 1/1/0/7
[SSPZX_S7506X-Onu1/1/0/7:1]display epon onu-update interface Olt 1/1/0/7
Port      Model      Version      Protocol      State
Onu1/1/0/7:1  ET908-H-POE-W  104          CTC           Updating(100%)
Onu1/1/0/7:2  ET908-H-POE-W  104          H3C          Not Configured
Onu1/1/0/7:3  ET908-H-POE-W  104          H3C          Not Configured
Onu1/1/0/7:4  ET908-H-POE-W  104          H3C          Not Configured
Onu1/1/0/7:5  ET908-H-POE-W  104          H3C          Not Configured
Onu1/1/0/7:6  ET908-H-POE-W  104          H3C          Not Configured
Onu1/1/0/7:7  ET908-H-POE-W  104          H3C          Not Configured
Onu1/1/0/7:8  ET924-H-POE    113          H3C          Not Configured
Onu1/1/0/7:9  ET924-H-POE    113          H3C          Not Configured
Onu1/1/0/7:10 ET908-H-POE-W  104          H3C          Not Configured
Onu1/1/0/7:11 ET908-H-POE-W  104          H3C          Not Configured
Onu1/1/0/7:12 ET908-H-POE-W  105          H3C          Not Configured
Onu1/1/0/7:13 ET908-H-POE-W  104          CTC           Failed

ONUs found: 13
[SSPZX_S7506X-Onu1/1/0/7:1]display epon onu-update interface on
[SSPZX_S7506X-Onu1/1/0/7:1]display epon onu-update interface Onu 1/1/0/7:1
Port      Model      Version      Protocol      State
Onu1/1/0/7:1  ET908-H-POE-W  104          CTC           Updating(100%)

ONUs found: 1
[SSPZX_S7506X-Onu1/1/0/7:1]display epon onu-update interface Onu 1/1/0/7:1
Port      Model      Version      Protocol      State
Onu1/1/0/7:1  ET908-H-POE-W  104          CTC           Updating(100%)

ONUs found: 1
[SSPZX_S7506X-Onu1/1/0/7:1]display epon onu-update interface Onu 1/1/0/7:1
Port      Model      Version      Protocol      State
Onu1/1/0/7:1  ET908-H-POE-W  104          CTC           Updating(100%)

ONUs found: 1
[SSPZX_S7506X-Onu1/1/0/7:1]display epon onu-update interface Onu 1/1/0/7:1
Port      Model      Version      Protocol      State
Onu1/1/0/7:1  ET908-H-POE-W  104          CTC           Failed

ONUs found: 1
[SSPZX_S7506X-Onu1/1/0/7:1]

```

过程分析

- 1、先尝试update onu type ET908-H-POE-W protocol-type h3c filename flash:/ET908HPOEW105.app
把protocol-type改成h3c试一下
 - 2、如果第一条方式不行的话，麻烦尝试：
104版本的ONU，先把ftth下的update命令删除，然后等30分钟左右，然后再对104版本的onu下的update命令删除，然后执行
update onu protocol-type ctc filename flash:/ET908HPOEW105.app
- 以上方式尝试过还是不行，检查版本文件MD5值发现与源版本文件的不一致，重新上传版本文件后升级成功。

解决方法

重新上传正确版本文件。