

## 知 Loopback-detection Function Not Working For S5600

董亮 2006-10-26 发表

### Loopback-detection Function Not Working For S5600

#### I Description of the Problem

When enable loopback-detection function on switch under the version S5600-VRP310-R1510P06 、 S5600-VRP310-R1510P07,loop-network of port could not be detected.

#### II Analysis of the issue

Switch which enables loopback-detection function could not send loopback-detection packet,so it results in the loopback-detection function not working.

#### III Solution

This problem exists only in version S5600-VRP310-R1510P06 、 S5600-VRP310-R1510P07.Users are able to apply version S5600-VRP310-R1510P05 and older, or update to version which will be released after version S5600-VRP310-R1510P07 to solve the issue ,If the function is needed.