

知 What are precautions for remote upgrade of VRP3.3 version on the Quidway R2631E

冷志宇 2007-09-27 发表

Q: What are precautions for remote upgrade of VRP3.3 version on the Quidway R2631E?

A: When vrp3.3-release 0001 is upgraded to vrp3.3 release 0002 on the Quidway R2631E, the configuration of all ports is lost because the hardware slot numbers are identified differently for two versions. It is recommended to upgrade the version locally. (This problem does not occur to the Quidway R3680E.)