Do the MAC, ARP and Routing Tables Need to Be Learnt Again after Active /Standby Switchover of the 95500 Series

孟维佳 2007-02-27 发表

MAC need to be learnt again, ARP collected again and the routing table learnt again.