某单位 S7503X 升级之后卡在加载界面

软件升级/降级　　**赵广旭**　　2022-10-09 发表

问题描述

当前版本7624P09,升级到了7596P10，卡死了：

```
[H3C]dis dev
[H3C]dis device
Slot No. Brd Type              Brd Status   Subslot  Sft Ver             Patch Ver
 0        LSQM3SUPA0           Master       0        S7500X-7624P09      None
 1        LSQM3SUPA0           Standby      0        S7500X-7624P09      None
 2        LSQM1TGS48RFE0       Normal       0        S7500X-7624P09      None
 3        LSQM1TGS48RFE0       Normal       0        S7500X-7624P09      None
 4        NONE                 Absent       0        NONE                None
[H3C]
```

```
BootWare Size        : 896KB
Flash Size           : 4MB
BASIC CPLD Version   : 001
EXTENDED CPLD Version : 001
PCB Version          : Ver.A

BootWare Validating...
Press Ctrl+B to access EXTENDED-BOOTWARE MENU...
Loading the main image files...
Loading file flash:/S7500X-CMW710-SYSTEM-R7596P10.bin.................Done.
Loading file flash:/S7500X-CMW710-FREERADIUS-R7596P10.bin........Done.
Loading file flash:/S7500X-CMW710-BOOT-R7596P10.bin.........................
Done.

Image file flash:/S7500X-CMW710-BOOT-R7596P10.bin is self-decompressing.....
.Done.
System image is starting...
```

Ready

过程分析

主控板LSQM3SUPA0 7596P10不支持。

解决方法

主控板不支持，无法升级