

知 SecPath U200-M 端口不时掉线？

接口板 其他 蜀天下 2017-11-22 发表

问题描述

SecPath U200-M

interface GigabitEthernet0/1 固定外网IP

interface GigabitEthernet0/2 连接公司内网 (S5120)

现在问题interface GigabitEthernet0/2不定时掉线，四五分钟后又正常，

有时有日志记录，有时没有

日志：

2017-09-08 10:36 发现掉线

2017-09-08 10:41 正常日志记录：

Sep 8 10:38:56:469 2017 WEB Warning admin logged in from 192.168.1.5

Sep 8 10:38:42:514 2017 WEB Warning admin failed to log in from 192.168.1.5

Sep 8 10:38:28:546 2017 WEB Warning admin failed to log in from 192.168.1.5

Sep 8 10:38:03:654 2017 WEB Warning admin logged out from 192.168.1.5

Sep 8 10:37:57:609 2017 SHELL Warning SSH user admin failed to login from 192.168.2.105 on VTY0.

Sep 8 10:36:32:257 2017 IFNET Warning Line protocol on the interface GigabitEthernet0/2 is UP

Sep 8 10:36:32:257 2017 IFNET Warning GigabitEthernet0/2: link status is UP

Sep 8 10:36:29:757 2017 IFNET Warning Line protocol on the interface GigabitEthernet0/2 is DOWN
WN

Sep 8 10:36:29:757 2017 IFNET Warning GigabitEthernet0/2: link status is DOWN

Sep 8 10:36:23:757 2017 IFNET Warning Line protocol on the interface GigabitEthernet0/2 is UP

Sep 8 10:36:23:757 2017 IFNET Warning GigabitEthernet0/2: link status is UP

Sep 8 10:36:20:757 2017 IFNET Warning Line protocol on the interface GigabitEthernet0/2 is DOWN
WN

Sep 8 10:36:20:757 2017 IFNET Warning GigabitEthernet0/2: link status is DOWN

Sep 8 10:32:50:758 2017 IFNET Warning Line protocol on the interface GigabitEthernet0/2 is UP

Sep 8 10:32:50:758 2017 IFNET Warning GigabitEthernet0/2: link status is UP

Sep 8 10:32:47:758 2017 IFNET Warning Line protocol on the interface GigabitEthernet0/2 is DOWN
WN

Sep 8 10:32:47:757 2017 IFNET Warning GigabitEthernet0/2: link status is DOWN

发生问题时，设备面板端口指示灯正常闪动

处理：网线，两设备端口都换，问题还时有发生，这个情况是什么问题？

解决方法

替换的网线接到别的设备上是否会出现端口也up、down呢。如果没有，可以中间串个设备，看下是不是协商，兼容问题

答案来自于 my8023