

知 S10508X-V设备是否支持包过滤出方向带vpn实例的rule

ACL

packet-filter

李先福

2020-04-14 发表

问题描述

不涉及

解决方法

不支持，下发会报错

[Spine-GigabitEthernet1/2/0/3]packet-filter 3000 outbound

Failed to apply or refresh IPv4 ACL 3000 to the outbound direction of interface GigabitEthernet1/2/0/3. The ACL is not supported.

#

acl number 3000

rule 10 permit ip vpn-instance spi source 24.82.0.0 0.0.31.255

rule 15 permit ip vpn-instance spi source 10.219.128.0 0.0.31.255

rule 50 deny tcp destination-port range 135 139

rule 55 deny tcp destination-port eq 3389

rule 60 deny tcp destination-port eq 445

rule 255 permit ip vpn-instance spi source 10.218.0.0 0.1.255.255 destination 24.82.0.0 0.0.31.255

rule 260 permit ip vpn-instance spi source 10.218.0.0 0.1.255.255 destination 10.219.128.0 0.0.31.25

5

rule 455 deny tcp destination 24.82.0.0 0.0.31.255 ack 0

rule 460 deny tcp destination 10.219.128.0 0.0.31.255 ack 0

#