

## 知 Cannot modify the AP configuration generated by auto-ap?

Wireless 龚训杰 2020-12-11 Published

### Problem Description

The system does not support modifying the AP service template in auto-ap mode.  
The prompt is as follows: [H3C]wlan ap auto\_001 Info: AP is auto-configured-ap. Can not perform the operation.

### Solution

Solution: Use the wlan auto-ap persistent command to convert the automatically generated "auto\_001" into a permanent configuration and then modify it:  
[H3C]wlan auto-ap persistent name auto\_001