

Serial接口打环后display intface Serial xxx不显示loopback is detected

E1PoS 张帅杰 2021-10-27 发表

问题描述

在传输设备上打环后,用命令display intface Serial xxx 看不到loopback is detected的标志,

```
Serial xxx:0
Current state: UP
Line protocol state: DOWN
Description: connect to 10.17.0.1/24
Bandwidth: 2048000 bps
Maximum transmission unit: 1550
Hold timer: 10 seconds, retry times: 5
Derived from 10.17.0.1, Unframed mode, Baudrate is 2048000 bps
Internet address: 10.17.0.1 (Primary)
Link layer protocol: PPP
LCP: stopped
Port priority: 0
Last clearing of counters: Never
CRC type is 16-bit
Last 300 seconds input: 0 packets/sec, 0 bytes/sec
Last 300 seconds output: 0 packets/sec, 2 bytes/sec
Input(total): 0 packets, 0 bytes
```

解决方法

运营商侧打环失败导致，重新打环后 在设备上display intface Serial xxx 可以看到Link layer protocol is PPP, loopback is detected

