

知 MSR5660 RT-SPU-100-X1板卡三层接口配置ip verify 提示不支持

以太网接口

IP Source Guar

彭旭

2022-01-15 发表

问题描述

MSR5660 RT-SPU-100-X1板卡三层接口配置ip verify 提示不支持，具体提示如下：

```
interface GigabitEthernet2/0/1
```

```
port link-mode route
```

```
description juyuwang-ip
```

```
combo enable copper
```

```
ip address 192.168.0.1 255.255.252.0
```

```
#
```

```
return
```

```
[H3C zzpost-GigabitEthernet2/0/1]ip verify source ip-address mac-address
```

```
Failed to enable IP source guard function on slot 2. Reason: Not support.
```

解决方法

经确认，该特性为二层特性，SPU-100-X1三层接口不支持进行IP与MAC绑定

