

知 某局点过F1060能ping通外网，但不能打开web界面

Web防护 杨雅伦 2022-02-28 发表

组网及说明

不涉及

问题描述

如题

过程分析

1、debug显示被应用识别阻断

```
*Feb 26 13:44:45:208 2022 waiwang_FW FILTER/7/PACKET: -Context=1; The packet is denied by Dim. Src-ZOne=Trust, Dst-ZOne=Untrust; If-In=GigabitEthernet1/0/15(16), If-Out=GigabitEthernet1/0/1(2); Packet Info:Src-IP=192.168.3.62, Dst-IP=114.114.114.114, VPN-Instance=, Src-MacAddr=8465-69f2-6201,Src-Port=60977, Dst-Port=53, Protocol=UDP(17), Application=dns(574), SecurityPolicy=any, Rule-ID=0.
```

2、查看设备上做了应用识别且缺省阻断

```
#  
uapp-control  
policy default-action deny  
#
```

解决方法

调整配置为允许即可

uapp-control

policy default-action permit

