

问题描述

本地镜像, 二层聚合口做目的端口, 有两个接口没有流量

#

```
interface Bridge-Aggregation1
description TO-SHGH-GX-100G
mirroring-group 1 monitor-port
```

#

```
Aggregate Interface: Bridge-Aggregation1
Aggregation Mode: Static
Loadsharing Type: Shar
Management VLANs: None
```

Port	Status	Priority	Oper-Key		
HGE1/0/1(R)	S	32768	1		
HGE1/0/2	S	32768	1		
HGE1/0/3	S	32768	1		
HGE1/0/4	S	32768	1		
HGE1/0/5	S	32768	1		
HGE1/0/6	S	32768	1		
HGE1/0/7	S	32768	1		
HGE1/0/8	S	32768	1		
HGE1/0/11	S	32768	1		
HGE1/0/12	S	32768	1		
HGE1/0/1		100	6462330	--	--
HGE1/0/2		100	6470651	--	--
HGE1/0/3		100	6727831	--	--
HGE1/0/4		100	6698896	--	--
HGE1/0/5		100	6682336	--	--
HGE1/0/6		100	6708644	--	--
HGE1/0/7		100	6419016	--	--
HGE1/0/8		100	6504715	--	--
HGE1/0/11		0	0	--	--
HGE1/0/12		0	0	--	--

过程分析

镜像的流量只能在聚合组的前8个端口上分担，所以后面两个端口没流量

解决方法

产品规格限制，无法修改

