

知 某局点S125CR display device 看板卡有2个master

其他硬件相关 柯辉 2023-03-27 发表

组网及说明

Slot	Type	State	Subslot	Soft Ver	Patch Ver
0	LSXM1CMUR1	master	0	S12508CR-115	None
1	LSXM1CMUR1	Standby	0	S12508CR-115	None
2	LSXM1SUPKR1	Master	0	S12508CR-5111	R5111H15
3	LSXM1SUPKR1	Standby	0	S12508CR-5111	R5111H15
4	LSXM1CGQ48KBR1	Normal	0	S12508CR-5111	R5111H15
5	LSXM1CGQ48KBR1	Normal	0	S12508CR-5111	R5111H15
6	LSXM1CGQ48KBR1	Normal	0	S12508CR-5111	R5111H15
7	LSXM1CGQ48KBR1	Normal	0	S12508CR-5111	R5111H15
8	LSXM1CGQ48KBR1	Normal	0	S12508CR-5111	R5111H15
9	LSXM1CGQ48KBR1	Normal	0	S12508CR-5111	R5111H15
10	LSXM1CGQ48KBR1	Normal	0	S12508CR-5111	R5111H15
11	LSXM1CGQ48KBR1	Normal	0	S12508CR-5111	R5111H15
12	LSXM1SFK08GR1	Normal	0	S12508CR-5111	R5111H15
13	LSXM1SFK08GR1	Normal	0	S12508CR-5111	R5111H15
14	LSXM1SFK08GR1	Normal	0	S12508CR-5111	R5111H15
15	LSXM1SFK08GR1	Normal	0	S12508CR-5111	R5111H15
16	LSXM1SFK08GR1	Normal	0	S12508CR-5111	R5111H15
17	LSXM1SFK08GR1	Normal	0	S12508CR-5111	R5111H15
18	LSXM1SFK08GR1	Normal	0	S12508CR-5111	R5111H15
19	LSXM1SFK08GR1	Normal	0	S12508CR-5111	R5111H15
20	LSXM1SFK08GR1	Normal	0	S12508CR-5111	R5111H15

告警信息

暂不涉及

问题描述

暂不涉及

过程分析

对于该情况为正常现象，0、1是监控板，2、3是主控

监控板不能同时更换，要有一个在位

其他的看看官网手册吧

http://www.h3c.com/cn/d_202101/1379773_30005_0.htm#_Toc44592372

解决方法

暂不涉及

