

厕除OSPFV3进程提示The ospfv3 process is smoothing. please try later

OSPF **张帅杰** 2023-11-16 发表

在设备上删除某一个OSPFV3进程或删除rout-id时提示The ospfv3 process is smoothing. please try lat er。 导致相关的命令一直删除不了

解决方法

主备主控板倒换会概率性触发这个问题

解决方法: 1. 升级到R8385P17 版本

2. 开启了进程NSR情况下,重启主控板的OSPF/OSPFV3进程:

例: <H3C>process restart name ospfv3d slot 1

Manually stopping or restarting a process can severely impact device operation. Use these commands only under the guidance of H3C engineers. Continue? [Y/N]:y

Restarting the process ospfv3d[530] on slot 1 ... Succeeded.

注意: 1.开启了NSR一般对其他的OSPF进程是没有影响的,挂住的OSPF进程会有一个LOADING to FULL的过程。

2.执行了上述命令后相应的OSPF进程就运行在备用主控上了,可以用process restart name ospfv3d sl ot x 再让其切到主用主控。