

知 不想显示闪断告警、重复告警、未知告警和未加入iMC设备告警的分析告警

李大维 2017-12-25 发表

在告警系统中，经常可以看到如下的分析告警：

Service

Alarm

Report

System

Query Devices

All Alarms

Real-Time Alarms

Alarm and Notification Settings

Filtering Trap

Browse Trap

Add to My Favorite

Recover

Acknowledge

Delete

More

Alarm Source, Description

Level	Alarm Source	Type	Description	Recovery	Ack Status	Alarm at	Recovered at	Persisted for
☐	NCS-OG-03-SW01(10.2.2.66)	IMC	IMC alarm system found event (The interface GigabitEthernet4/0/31 is UP) and event (The interface GigabitEthernet4/0/31 is DOWN) had 5 intermittent failures from 2017-05-23 13:07:16 to 2017-05-23 13:09:18.	Unrecover ed	Unacknowledge d	2017-05-23 13:09:18		58 Sec
☐	NCS-OG-03-SW01(10.2.2.66)	IMC	IMC alarm system found event (The interface GigabitEthernet4/0/31 is UP) and event (The interface GigabitEthernet4/0/31 is DOWN) had 5 intermittent failures from 2017-05-23 13:06:10 to 2017-05-23 13:06:54.	Unrecover ed	Unacknowledge d	2017-05-23 13:06:54		3 Min 22 Sec
☐	NCS-OG-03-SW01(10.2.2.66)	IMC	IMC alarm system found event (The interface GigabitEthernet4/0/31 is UP) and event (The interface GigabitEthernet4/0/31 is DOWN) had 5 intermittent failures from 2017-05-23 13:01:18 to 2017-05-23 13:03:52.	Unrecover ed	Unacknowledge d	2017-05-23 13:03:52		6 Min 24 Sec
☐	NCS-OG-03-SW01(10.2.2.66)	IMC	IMC alarm system found event (The interface GigabitEthernet4/0/31 is UP) and event (The interface GigabitEthernet4/0/31 is DOWN) had 5 intermittent failures from 2017-05-23 12:59:49 to 2017-05-23 13:01:18.	Unrecover ed	Unacknowledge d	2017-05-23 13:01:18		8 Min 58 Sec
☐	NCS-OG-03-SW01(10.2.2.66)	IMC	IMC alarm system found event (The interface GigabitEthernet4/0/31 is UP) and event (The interface GigabitEthernet4/0/31 is DOWN) had 5 intermittent failures from 2017-05-23 12:59:00 to 2017-05-23 12:59:00.	Unrecover ed	Unacknowledge d	2017-05-23 12:59:00		11 Min 16 Sec
☐	NCS-OG-03-SW01(10.2.2.66)	IMC	IMC alarm system found event (The interface GigabitEthernet4/0/31 is UP) and event (The interface GigabitEthernet4/0/31 is DOWN) had 5 intermittent failures from 2017-05-23 12:52:50 to 2017-05-23 12:54:43.	Unrecover ed	Unacknowledge d	2017-05-23 12:54:43		15 Min 33 Sec
☐	NCS-OG-03-SW01(10.2.2.66)	IMC	IMC alarm system found event (The interface GigabitEthernet4/0/31 is UP) and event (The interface GigabitEthernet4/0/31 is DOWN) had 5 intermittent failures from 2017-05-23 12:50:56 to 2017-05-23 12:52:34.	Unrecover ed	Unacknowledge d	2017-05-23 12:52:34		17 Min 42 Sec

但是有时候这些告警产生的过多，会影响观察其他告警的信息，因此我们有时候不想看到这些分析告警信息。

客户的环境用闪断、重复、未知、未加入iMC设备的trap频繁产生。

重复Trap过滤	屏蔽重复接收到的相同Trap，并可在达到阈值条件时产生新告警通知用户。		
闪断Trap分析	分析接收到的闪断Trap，并可在达到阈值条件时产生新告警通知用户。		
未知Trap过滤	屏蔽接收到的未知Trap，并可在达到阈值条件时产生新告警通知用户。		
未加入本系统设备Trap过...	屏蔽接收到的未加入本系统设备Trap，并可在达到阈值条件时产生新告警通知用户。		

这些分析告警信息会由设备匹配此trap时大量产生。

在trap过滤的预制的4条过滤规则中，去勾选生成告警的选项。

解决掉闪断、重复、未知、未加入的环境问题。