

知 S10510交换机不识别防火墙板卡LSUM3FWCEA0解决办法

单板

李聪

2018-01-12 发表

Q: 交换机上插了一块防火墙板卡LSUM3FWCEA0, 在交换机上面display device verbose看到防火墙板卡fault:

=====display device verbose=====

Slot No.	Brd Type	Brd Status	Subslot	Sft Ver	Patch Ver
0	LSUM1FWCEAB0	Normal	0	S10500-7557	None
1	LSU1ADECEA0	Normal	0	S10500-7557	None
2	LSUM2TGS48SG0	Normal	0	S10500-7557	None
3	LSUM2GT48SE0	Normal	0	S10500-7557	None
4	NONE	Absent	0	NONE	None
5	LSUM1WCMX20RT	Normal	0	S10500-7557	None
6	NONE	Absent	0	NONE	None
7	NONE	Absent	0	NONE	None
8	NONE	Absent	0	NONE	None
9	NONE	Fault	0	NONE	None
10	LSUM1MPU10A0	Master	0	S10500-7557	None
11	LSUM1MPU10A0	Standby	0	S10500-7557	None
12	LSUM1FAB10A0	Normal	0	S10500-7557	None
13	LSUM1FAB10A0	Normal	0	S10500-7557	None

同时display logbuffer看到日志里面提示:

%Jan 12 18:03:48:444 2018 JY-HX-S10510 DRVPLAT/4/DrvDebug:

Please move the card in slot 9 to any one of slot 0 to slot 3.

A: 原因是这个交换机配置了防火墙板卡的时候, 只支持在slot 0到3槽位部署防火墙插卡, 交换机设备才可以识别防火墙板卡。