

**H3C S10500系列交换机R1208P06版本发布
公告**

一、使用范围及配套说明:

H3C S10500系列交换机R1208P06版本正式发布，发布范围为国内市场。版本配套关系请参考如下版本配套表:

产品系列	S10500 系列交换机
型号	S10504、S10508、S10508-V、S10512
内存	1G
FLASH	128M
BOOTROM版本号	交换机自带版本 (该版本号可在命令行任何视图下用display version命令查看)
目标文件名称	S10500-CMW520-R1208P06.bin
iMC版本号	iMC BIMS 7.0 (E0102) iMC EAD 7.0 (E0103) iMC EIA 7.0 (E0103) iMC MVM 7.0 (E0101P02) iMC NTA 7.0 (E0101P01) iMC PLAT 7.0 (E0102L01) iMC QoS 7.0 (E0102) iMC SHM 7.0 (E0101) iMC UBA 7.0 (E0101P01)
iNode版本号	iNode PC 7.0 (E0103)
SecBlade WCMB	WX6103-CMW520-R2115P19 and later
SecBlade FW	SECPATH1000FE&SECBLADEII-CMW520-R3166P13 and later
SecBlade AFC	SECBLADEAFD-CMW520-E3161 and later
SecBlade AFD	SECBLADEAFD-CMW520-E3161 and later
SecBlade ACG	SecPathACG2000&SecBladeACG-IMW110-E6117P12 and later
SecBlade NSM	SECBLADENSM-CMW520-R3106 and later
SecBlade LB	SECBLADELB-CMW520-R3204P17 and later
SecBlade SSL VPN	SECBLADESSLVPN-CMW340-E7111 and later
SecBlade IPS	SecBladeIPS-IMW110-E2110P10 and later
SecBlade WCMD	WX6103-CMW520-E2302 and later
SecBlade IAG	SECBLADEIAG-CMW520-R7508 and later
SecBlade WCMB	WX6103-CMW520-R2115P19 and later
备注	无

二、增减特性说明:

1 新增特性:

- LSU1GT24SE3 24-Port 1000BASE-T Ethernet Interface Board (RJ45)
- LSU1GP12SE3 12-Port 1000BASE-X Ethernet Optical Interface Board(SFP,LC)
- LSU1GP24SE3 24 Port 1000BASE-X Ethernet Optical Interface Board(SFP,LC)
- LSU1T24XGSE3 24-Port 1000BASE-T Gigabit Ethernet Interface(RJ45)+2-Port 10GBASE Ethernet Optical Interface Board(XFP,LC)
- LSU1P24XGSE3 24-Port 1000BASE-X Gigabit Ethernet Optical Interface(SFP,LC)+2-Port 10GBASE Ethernet Optical Interface Board(XFP,LC)
- LSU1GP24TSE3 16-Port 1000BASE-X Gigabit Ethernet Optical(SFP,LC) And 8-Port 10/100/1000BASE-T RJ45/1000BASE-X SFP Combo Interface Board
- LSU1GT40PSE3 40-Port 10/100/1000BASE-T Electrical(RJ45) And 8-Port 1000BASE-X Optical Ethernet Interface Board(SFP,LC),PoE

2 删除特性:

无

3 修改特性:

无

详细信息请参见随版本发布的文档《H3C_S10500-CMW520-R1208P06版本说明书(软件特性变更说明)》

三、相比前一版本解决的问题说明:

1. 201311180071

问题描述: 该报文被默认copy到cpu。

触发条件: ip报文携带option信息

2. 201311110039

问题现象: PBR部分流规则不生效。

问题产生条件: 下发PBR时,如果PBR的规则acl存在流规则互相涵盖。

3. 201309060356

问题现象: 设备不识别该类型光模块。

问题产生条件: LSU1QGS4SF、LSU1QGS8SF单板上插入40G LR4光模块

如要完整的了解该版本累计解决的软件BUG, 请参看配套发布的《H3C_S10500-CM W520-R1208P06_版本说明书》。