

Why the IP Address Cannot Be Configured Directly at the POS Port

孟维佳 2007-01-31 发表

On a router, the IP addresses can be configured at various ports. However, on a switch, the IP addresses are usually configured at the VLAN virtual interfaces. To be consistent and convenient, S9500 does not configure IP addresses directly for the POS port, but treat the POS port as an ordinary port and specify a VLAN for it before configuring IP addresses at the VLAN virtual interface. The VLAN has no actual meaning and it can only contain this POS port and no other POS ports or Ethernet ports.