

知 When using VoIP, the Quidway mid-range-and-low-end routers detect that the telephone can ring but both parties in a call cannot hear each other during the interworking between VRP1.74-0010 and VRP1.74-0105. Why

冷志宇 2007-09-27 发表

Q: When using VoIP, the Quidway mid-range-and-low-end routers detect that the telephone can ring but both parties in a call cannot hear each other during the interworking between VRP1.74-0010 and VRP1.74-0105. Why?

A: VRP1.74-0010 checks the H323 descriptor of both parties in a call, while VRP1.74-0105 does not check the H323 descriptor of both parties in a call. Solution: Both of them shall be upgraded to VRP1.74-0105. Otherwise, you can configure the same H323 descriptor: h323 description **** (any character string like huawei, which shall be the same for both parties) for both parties in the VOICE-SETUP mode.