



## H3C S3600为何下发某些ACL rules会失败?

赵国卫 2008-06-30 发表

有如下ACL:

```
acl number 3001
```

```
rule 30 deny tcp destination-port eq 135
```

```
rule 31 deny udp destination-port eq 135
```

```
rule 32 deny tcp destination-port eq 137
```

```
rule 33 deny udp destination-port eq ne
```

```
rule 48 deny tcp source-port gt 10000
```

将ACL下发到端口时, 发现rule 48下发失败

```
packet-filter inbound ip-group 3001
```

```
Applying Acl 3001 rule 48 failed!
```

Reason: This type of ACL rule is not supported by the command which is attempting to use the ACL!

这是因为H3C S3600系列不支持指定端口范围的ACLRule, 同样在H3C S5600系列交换机上也不支持此类ACL Rule。