



The notices about VRRP of SR66 series router

赵博 2008-09-01 发表

The notices about VRRP of SR66 series router

The virtual IP address of backup group can't be 0.0.0.0, 255.255.255.255, loopback address, D and E class address, and other invalid address (eg.0.0.0.1).

The virtual and interface IP address must be in the same subnet, otherwise, VRRP doesn't work.