

知 S7503E+板卡LSQM1GP24TSC0光口灯闪烁问题

[二层环路检测](#)[以太网接口](#)[环路检测](#)[cowco](#)

2017-11-15 发表

组网及说明

H3C Comware Platform Software

Comware Software, Version 5.20, Release 6708P03

Copyright (c) 2004-2013 Hangzhou H3C Tech. Co., Ltd. All rights reserved.

H3C S7503E uptime is 0 week, 0 day, 0 hour, 3 minutes

MPU(M) 0:

Uptime is 0 weeks,0 days,0 hours,3 minutes

H3C S7503E MPU(M) with 1 BCM1125H Processor

BOARD TYPE: LSQ1SRP1CB

DRAM: 512M bytes

FLASH: 64M bytes

NVRAM: 512K bytes

PCB 1 Version: VER.B

PCB 2 Version: VER.B

Bootrom Version: 500

CPLD 1 Version: 007

CPLD 2 Version: 007

Release Version: H3C S7503E-6708P03

Patch Version : None

Slot 1 Without Board

LPU 2:

Uptime is 0 weeks,0 days,0 hours,1 minutes

H3C S7503E LPU with 1 BCM1122 Processor

BOARD TYPE: LSQ1TGX2SC

DRAM: 512M bytes

FLASH: 0M bytes

NVRAM: 0K bytes

PCB 1 Version: VER.C

PCB 2 Version: VER.B

Bootware Version: 306

CPLD 1 Version: 003

CPLD 2 Version: 004

Release Version: H3C S7503E-6708P03

Patch Version : None

LPU 3:

Uptime is 0 weeks,0 days,0 hours,2 minutes

H3C S7503E LPU with 1 BCM1122 Processor

BOARD TYPE: LSQ1GP24TSC

DRAM: 512M bytes

FLASH: 0M bytes

NVRAM: 0K bytes

PCB 1 Version: VER.A

Bootware Version: 306

CPLD 1 Version: 002

CPLD 2 Version: 002

Release Version: H3C S7503E-6708P03

Patch Version : None

Slot 4 Without Board

[ReNongZhu-S7503E]dis dev

[ReNongZhu-S7503E]dis device

Slot No.	Brd Type	Brd Status	Subslot Num	Sft Ver	Patch Ver
0	LSQ1SRP1CB	Master	0	S7500E-6708P03	None
1	NONE	Absent	0	NONE	None
2	LSQ1TGX2SC	Normal	0	S7500E-6708P03	None
3	LSQ1GP24TSC	Normal	0	S7500E-6708P03	None
4	NONE	Absent	0		

问题描述

交换机型号S7503E，板卡LSQM1GP24TSC0（位于3槽），其中3到10口插上光纤后，这几个光口闪烁频率一致，大概0.5S闪一次，就像故障灯闪烁频率那样。不像平时的快速闪烁
开始以为是业务量小，但业务运行后还是如此。
端口状态正常UP，将所有端口都shutdown后只剩一个口依旧如此（排除环路），光模块标签是H3C的。
连上S5560上则闪烁频率快，没有出现此问题。
其次网段可通。

究竟是什么原因？

解决方法

对转发有影响么？没有影响无需关注，接口的芯片不同可能导致协商不一致。

答案来自于 墨峰