绿洲平台 吴孝禹 2020-03-20 发表

云AP结合绿洲

问题描述

某局点查看AP日志发现 不定时出现服务模板关闭打开的现象

查看日志发现如下日志:

%Mar 16 10:35:02:532 2020 H3C STAMGR/6/SERVICE_OFF: BSS 04d7-a5b8-c060 was deleted aft er service template 1 with SSID js was unbound from radio 1 on AP fatap. Reason: Disabled service t emplate.

%Mar 16 10:35:02:537 2020 H3C STAMGR/6/STAMGR_CLIENT_OFFLINE: Client ec7d-111f-4fc1 went offline from BSS 04d7-a5b8-c070 with SSID js on AP fatap Radio ID 2. State changed to Unauth . Reason:Service template disabled.

%Mar 16 10:35:02:538 2020 H3C STAMGR/6/SERVICE_OFF: BSS 04d7-a5b8-c070 was deleted aft er service template 1 with SSID js was unbound from radio 2 on AP fatap. Reason: Disabled service t emplate.

%Mar 16 10:35:02:857 2020 H3C STAMGR/6/SERVICE_ON: BSS 04d7-a5b8-c060 was created after service template 1 with SSID js was bound to radio 1 on AP fatap. %Mar 16 10:35:02:859 2020 H3C STAMGR/6/SERVICE_ON: BSS 04d7-a5b8-c070 was created after service template 1 with SSI D js was bound to radio 2 on AP fatap.

服务模板在1s之内关闭重新开启,对于reason为Disabled service template,一般来说均为命令行操作 导致的服务模板关闭,而查看display history-command all 未发现对应时间内有操作记录。

与研发沟通后了解到,云ap 绿洲在下发配置的时候,会先关闭服务模板然后再开启服务模板,这个是 一个正常现象,可以不用关注。