

(m) Cannot modify the AP configuration generated by auto-ap?

Wireless 龚训杰 2020-12-11 Published

The system does not support modifying the AP service template in auto-ap mode.

The prompt is as follows: [H3C]wlan ap auto_001 Info: AP is auto-configured-ap. Can not perform the operation.

Solution: Use the wlan auto-ap persistent command to convert the automatically generated

"auto_001" into a permanent configuration and then modify it:

[H3C]wlan auto-ap persistent name auto_001