

## 知 Why can't the registered AP be TELNET?

Wireless

河然·吐尔生别克

2020-12-11 Published

### Problem Description

Why can't the registered AP be TELNET?

### Solution

It is normal to APs that are successfully registered to the AC cannot be TELNET, because in principle, a Fit AP does not need to be configured separately and is managed by the AC. If an AP can be TELNET, it means that the AP is not registered.