

知 【Nimble】扩容bank b的flash cache的硬盘容量是否必须与bank a相同

存储配置 高成良 2021-05-17 发表

问题描述

[nimble]扩容bank b的flash cache的硬盘容量是否必须与bank a相同

解决方法

可以不同，但同一bank的容量需要相同。

Caution!

Before you install the new drives:

- You must update the array to NimbleOS 3.3.x (for CS1000, CS3000, CS5000, CS7000), or NimbleOS

3.4.x (for CS1000H) before adding new SSDs in each drive carrier (Drive B). Failing to do so may result in unavailability of service.

- **Important!** All Drive A sleds must be fully populated before installing SSDs in Drive B sleds.
- The pack of SSDs must all be the same capacity.

Note: The SSDs in Drive B can be different capacities than the SSDs already installed in Drive A.

