

知 HPE DL385 Gen10 Plus 服务器 安装Windows Server 2019常用驱动

Windows系统安装 驱动安装升级 张帅 2023-02-02 发表

问题描述

HPE DL385 Gen10 Plus 服务器 安装Windows Server 2019常用驱动

解决方法

一、适用范围

机型：DL385 Gen10 Plus

操作系统：Microsoft Windows Server 2019

二、驱动下载

如果想要到官网下载最新驱动请参考如下方法：

<https://zh1.hpe.com/html/zh1hpe001680/>

如果您仍没有找到驱动，可以尝试如下链接，本文章会不定期进行更新，请您参考

| 驱动类别 | 当前版本 | | 下载地址 |
|----------------------------------------|---------------|-----------|----------------------|
| | 版本号 | 发布日期 | |
| 板载i350 网卡 | 14.0.2.0 | 2024.3.25 | 驱动下载 |
| iLO 5 Automatic Server Recovery Driver | 4.7.1.0(E) | 2024.4.19 | 驱动下载 |
| iLO 5 Channel Interface Driver | 4.7.1.0(E) | 2024.4.19 | 驱动下载 |
| 芯片组 | 6.2.26.720 | 2024.4.19 | 驱动下载 |
| 板载显卡 | 9.15.1.248(E) | 2024.4.19 | 驱动下载 |

点击如上超链接后，可以参考如下图文进行驱动的安装和信息的了解（注：如下图片仅做参考，实际内容以驱动链接打开后显示为准）

点击下方"Installation Instructions"查看驱动的安装方法

Compatibility Release Notes Revision History Important **Installation Instructions** Enhancements

To ensure the integrity of your download, HPE recommends verifying your results with the following SHA-256 Checksum values:

51fb619a0fa8f8921b532b5ffa348300e6c497bdb25e4001cdd08b0714886 cp050039.compsig
5565ffaa96cb31f922dda10dff5abe3ef6d5639336e044636c750933daabc6e2 cp050039.exe

Reboot Requirement:
Reboot may be required after installation for updates to take effect and hardware stability to be maintained.

Installation:
Place the Smart Component in a temporary directory, then double-click it to run.
Select .!install to start extracting to a temporary location on the hard drive.
Click the .!install button to perform the driver installation.

点击下方"Revision History"查看历史版本及修复的相关问题：

Compatibility Release Notes **Revision History** Important Installation Instructions Enhancements

Version: 4.7.1.0(C) (28 Sep 2022)
Enhancements
Upgrade Requirement:
Optional - Users should update to this version if their system is affected by one of the documented fixes or if there is a desire to utilize any of the enhanced functionality provided by this version.

- Added SHA384 signature

Version: 4.7.1.0(B) (5 Nov 2021)
Enhancements
Upgrade Requirement:
Optional - Users should update to this version if their system is affected by one of the documented fixes or if there is a desire to utilize any of the enhanced functionality provided by this version.

- Added support for Snap5 platforms

Version: 4.7.1.0 (23 Apr 2021)
Fixes
Upgrade Requirement:
Recommended - HPE recommends users update to this version at their earliest convenience.

- Fixed branding issue

