🗩 H3C无线接入点V7AP胖模式切换成瘦模式的经验案例

勿海产 2017-12-18 反表	杨海严	2017-12-18 发表
--------------------------	-----	---------------

软件升级

现场WA5530结合V7 AC (WX5540H) 部署, 一直无法注册成功。工程师console登录AP后, 发现是 胖模式,版本是Version 7.1.064, ESS 2329P01,现在配合AC使用必须将AP切换成瘦模式。 //连接console线,使用CRT或者超级终端新建serial(串口)连接,AP上电启动,console登录到AP上 System is starting ... Press Ctrl+D to access BASIC-BOOTWARE MENU Booting Normal Extended BootWare The Extended BootWare is self-decompressing..... ...Done. //不停地按Ctrl+B * H3C WA5530 BootWare, Version 7.10 ***** Copyright (c) 2004-2017 New H3C Technologies Co., Ltd. Compiled Date : Sep 25 2017 CPU Type : ARM CPU L1 Cache : 32KB CPU L2 Cache : 256KB CPU Clock Speed : 710MHz Memory Type : DDR3 SDRAM Memory Size : 512MB Memory Speed : 667MHz Flash Size : 128MB PCB Version : Ver.A BootWare Validating... Press Ctrl+B to access EXTENDED-BOOTWARE MENU ... Password recovery capability is enabled. Note: The current operating device is flash Enter < Storage Device Operation > to select device. / 输入回车 |<1> Boot System | |<2> Enter Serial SubMenu |<3> Enter Ethernet SubMenu |<4> File Control <5> Restore to Factory Default Configuration <6> Skip Current System Configuration |<7> BootWare Operation Menu |<8> Skip Authentication for Console Login |<9> Storage Device Operation |<0> Reboot _____ Ctrl+Z: Access EXTENDED ASSISTANT MENU Ctrl+F: Format File System Ctrl+C: Display Copyright Ctrl+Y: Change AP Mode Enter your choice(0-9): //输入Ctrl+F, 格式化flash Warning:All files on flash will be lost! Are you sure to format? [Y/N]Y //输入Y

Format success.

<1> Boot System
<2> Enter Serial SubMenu
<3> Enter Ethernet SubMenu
<4> File Control
<5> Restore to Factory Default Configuration
<6> Skip Current System Configuration
BootWare Operation Menu
<8> Skip Authentication for Console Login
<9> Storage Device Operation
<u> Redoot </u>
Ctrl+Z: Access EXTENDED ASSISTANT MENU
Ctrl+F: Format File System
Ctrl+C: Display Copyright
Ctrl+Y: Change AP Mode
Enter your choice(0-9): //输入Ctrl+Y,设置ap胖模式或者瘦模式
Please select the new mode
Current mode is Fat //提示当前是fat胖模式
NO. Mode
1 Fat Mode
2 Fit Mode
0 Exit
Enter your choice(0-2):2 // 捆/人之, 即加度模式
Warning:Change from fat mode to fit mode formats the storage medium! Are
vou sure to continue?[Y/NIY //输入Y,确认切换成fit瘦模
式
Formatted the storage medium successfully!
Changed to fit mode successfully! //修改成fit/瘦模式成功。此时可以将AP和AC连接好, AP上电启动
· 获取IP地址后,会王动向AC获取版本文件更新到flash中运行。另外一种方式,从AC的flash apimge目
获取IP地址后,会主动向AC获取版本文件更新到flash中运行。另外一种方式,从AC的flash apimge目录下导出wa5300.ipe文件手工传到AP上,具体步骤如下
获取IP地址后,会主动向AC获取版本文件更新到flash中运行。另外一种方式,从AC的flash apimge自录下导出wa5300.ipe文件手工传到AP上,具体步骤如下
获取IP地址后,会主动向AC获取版本文件更新到flash中运行。另外一种方式,从AC的flash apimge自录下导出wa5300.ipe文件手工传到AP上,具体步骤如下
狭眼IP地址后,会主动向AC狭取版本文件更新到flash中运行。另外一种方式,从AC的flash apimge自 录下导出wa5300.ipe文件手工传到AP上,具体步骤如下 ===================================
狭戦IP地址后,会王动向AC狭取版本文件更新到flash中运行。另外一种方式,从AC的flash apimge自 录下导出wa5300.ipe文件手工传到AP上,具体步骤如下
狭地IP地址后,会主动向AC获取版本文件更新到flash中运行。另外一种方式,从AC的flash apimge自 录下导出wa5300.ipe文件手工传到AP上,具体步骤如下
採取IP地址后,会主动向AC获取版本文件更新到flash中运行。另外一种方式,从AC的flash apimge自 录下导出wa5300.ipe文件手工传到AP上,具体步骤如下
狭眼IP地址后,会主动向AC狭取版本文件更新到flash中运行。另外一种方式,从AC的flash apimge自 录下导出wa5300.ipe文件手工传到AP上,具体步骤如下
获取IP地址后, 会主动问AC获取版本文件更新到flash中运行。另外一种方式, 从AC的flash apimge目 录下导出wa5300.ipe文件手工传到AP上, 具体步骤如下 =================================
採取IP地址后, 会主动向AC获取版本文件更新到flash中运行。另外一种方式, 从AC的flash apimge自 录下导出wa5300.ipe文件手工传到AP上, 具体步骤如下
採取IP地址后, 会主动向AC获取版本文件更新到flash中运行。另外一种方式, 从AC的flash apimge目 录下导出wa5300.ipe文件手工传到AP上, 具体步骤如下
採取IP地址后, 会王动向AC获取版本文件更新到flash中运行。另外一种方式, 从AC的flash apimge目 录下导出wa5300.ipe文件手工传到AP上, 具体步骤如下
获取IP地址后,会主动问AC获取版本文件更新到flash中运行。另外一种方式,从AC的flash apimge目 录下导出wa5300.ipe文件手工传到AP上,具体步骤如下 ====================================
获取IP地址后,会主动问AC获取版本文件更新到flash中运行。另外一种方式,从AC的flash apimge目 录下导出wa5300.ipe文件手工传到AP上,具体步骤如下
秋眼P地址后, 会王动向AC获取版本文件更新到flash中运行。另外一种方式, 从AC的flash apimge目 录下导出wa5300.ipe文件手工传到AP上, 具体步骤如下
获取IP地址后,会主动向AC获取版本文件更新到flash中运行。另外一种方式,从AC的flash apimge目 录下导出wa5300.ipe文件手工传到AP上,具体步骤如下
秋眼P地址后,会主动向AC获取版本文件更新到flash中运行。另外一种方式,从AC的flash apimge目 录下导出wa5300.ipe文件手工传到AP上,具体步骤如下
获取IP地址后, 会主动问AC获取版本文件更新到flash中运行。另外一种方式, 从AC的flash apimge目 录下导出wa5300.ipe文件手工传到AP上, 具体步骤如下
採取IP地理店,会主动问AC装取版本文件更新到Hash中运行。另外一种方式,从ACB/Hash apimge目 家下导出wa5300.ipe文件手工传到AP上,具体步骤如下
採取IP地址后,会主动向AC获取版本文件更新到flash中运行。另外一种方式,从AC的flash apimge目 家下导出wa5300.ipe文件手工传到AP上,具体步骤如下
採取IP地址后,会主动向AC获取版本文件更新到flash中运行。另外一种方式,从AC的flash apimge目 家下导出wa5300.ipe文件手工传到AP上,具体步骤如下
秋和P地址后, 会王动向AC获取版本文件更新到flash中运行。另外一种方式, 从AC的flash apimge目 家下导出wa5300.jpe文件手工传到AP上, 具体步骤如下
秋和P地理店, 会王动向AC获粮版本文件更新到Itash中运行。另外一种方式, 从ACB/Itash apimge目 录下导出wa5300.ipe文件手工传到AP上, 具体步骤如下
秋秋川P地址広, 会主动问AC装取版本文件更新到flash中运行。另外一种方式, MACEIIflash apimge目 录下导出wa5300.jpe文件手工传到AP上, 具体步骤如下
秋秋川P地址后,会主动问AC装取版本文件更新到flash中运行。另外一种方式,从AC的flash apimge目 录下导出wa5300.jpe文件手工传到AP上,具体步骤如下

<ensure be="" before="" downloading!="" modified="" parameter="" the=""></ensure>	1

======================================	
Note: & # 39;.& # 39; = Clear field.	
& # 39;-& # 39; = Go to previous field.	
Ctrl+D = Quit.	
Protocol (FTP or TFTP) :ftp tftp //tftp协议	
Load File Name :wa5300-fat.ipe	
:wa5300.ipe //瘦版本文件名称	
Target File Name :wa5300-fat.ipe	
。 :wa5300.ipe //瘦版本文件名称	
Server IP Address :192.168.1.18 192.168.0.10 //tftp服务器 (PC) 的IP地址	
Local IP Address :192.168.1.20 192.168.0.50 //AP本地的IP地址	
Subnet Mask 255 255 255 0 255 255 0 // 体码	
Gataway IP Address · :0000 //不田綸 百控回车	
Enter Ethernet SubManus	
Note:the operating device is flash	
<1> Download Image Program To SDRAM And Run	
<pre></pre>	
<3> Update Backup Image File	
<pre> <4> Download Files(*.*)</pre>	
<pre>I<5> Modify Ethernet Parameter</pre>	
I<0> Exit To Main Menu	
Ise and to main month	
Enter your choice(0-5): 2 //输入2,更新主镜像文件(更新版本)	
LoadingDor	ıe.
18165760 bytes downloaded!	
Image file wa5300-boot.bin is self-decompressing	
Saving file flash:/wa5300-boot.binDone.	
Image file wa5300-system.bin is self-decompressing	
Saving file flash:/wa5300-system.bin	
Done.	
======SubMenu>====================================	
Note:the operating device is flash	
<1> Download Image Program To SDRAM And Run	
<2> Update Main Image File	
<3> Update Backup Image File	
<pre><4> Download Files(*.*)</pre>	
<5> Modify Ethernet Parameter	
<pre> <0> Exit To Main Menu</pre>	
Enter your choice(0-5): 0 //轴入0, 返回	
======================================	
<1> Boot System	
<2> Enter Serial SubMenu	
<3> Enter Ethernet SubMenu	
<4> File Control	
<5> Restore to Factory Default Configuration	
I<6> Skip Current System Configuration	
I<7> BootWare Operation Menu	
Las Skin Authentication for Console Login	
- Storage Device Operation	

Ctrl+Z: Access EXTENDED ASSISTANT MENU Ctrl+F: Format File System Ctrl+C: Display Copyright * * H3C WA5530 BootWare, Version 7.10

Copyright (c) 2004-2017 New H3C Technologies Co., Ltd.

Compiled Date: Sep 25 2017CPU Type: ARMCPU L1 Cache: 32KBCPU L2 Cache: 256KBCPU Clock Speed: 710MHzMemory Type: DDR3 SDRAMMemory Size: 512MBMemory Speed: 667MHzFlash Size: 128MBPCB Version: Ver.A

BootWare Validating... Press Ctrl+B to access EXTENDED-BOOTWARE MENU... Loading the main image files... Loading file flash:/wa5300-system.bin......Done. Loading file flash:/wa5300-boot.bin......Done.

Extended BootWare Version is not equal,updating? [Y/N] Updating Extended BootWare......Done. BootWare updated,System is rebooting now. System is starting... Press Ctrl+D to access BASIC-BOOTWARE MENU Booting Normal Extended BootWare The Extended BootWare is self-decompressing...... ...Done.

* * H3C WA5530 BootWare, Version 7.09 * *

Copyright (c) 2004-2017 New H3C Technologies Co., Ltd.

Compiled Date: Jun 23 2017CPU Type: ARMCPU L1 Cache: 32KBCPU L2 Cache: 256KBCPU Clock Speed: 710MHzMemory Type: DDR3 SDRAMMemory Size: 512MBMemory Speed: 667MHzFlash Size: 128MBPCB Version: Ver.A

BootWare Validating... Press Ctrl+B to access EXTENDED-BOOTWARE MENU... Loading the main image files... Loading file flash:/wa5300-system.bin......Done. Loading file flash:/wa5300-boot.bin......Done.

Image file flash:/wa5300-boot.bin is self-

decompressing.....Done.

System image is starting...

Startup configuration file does not exist. Line con0 is available.

Press ENTER to get started.

<H3C> //升级成功 %Dec 15 18:56:11:669 2017 H3C SHELL/5/SHELL_LOGIN: Console logged in from con0.

先Ctrl+F格式化flash,再Ctrl+Y选择瘦模式,最后加载版本。