

## 问题描述

HPE MicroServer Gen10 Plus v2 服务器安装Windows Server 2019常用驱动

## 解决方法

### 一、适用范围

机型：MicroServer Gen10 Plus v2

操作系统：Microsoft Windows Server 2019

### 二、驱动下载

如果想要到官网下载最新驱动请参考如下方法：

[HPE MicroServer Gen10 Plus v2 服务器常用驱动](#)

如果您仍没有找到驱动，可以尝试如下链接，本文章会不定期进行更新，请您参考

驱动类别	当前版本		下载地址
	版本号	发布日期	
Intel i350网卡	12.18.16.0	2023.11.1	<a href="#">驱动下载</a>
iLO 5 Automatic Server Recovery Driver	4.7.1.0(D)	2023.3.31	<a href="#">驱动下载</a>
iLO 5 Channel Interface Driver	4.7.1.0(D)	2023.3.31	<a href="#">驱动下载</a>
芯片组	10.1.18807.8279(B)	2022.9.28	<a href="#">驱动下载</a>
板载显卡	9.15.1.248(D)	2023.3.31	<a href="#">驱动下载</a>

点击如上超链接后，可以参考如下图文进行驱动的安装和信息的了解（注：如下图片仅做参考，实际内容以驱动链接打开后显示为准）

点击下方"Installation Instructions"查看驱动的安装方法

Compatibility Release Notes Revision History Important **Installation Instructions** Enhancements

To ensure the integrity of your download, HPE recommends verifying your results with the following SHA-256 Checksum values:

51fb19a0fa8f8921b532b5fffa348300e6c497dbdb25e4001cdd08b0714886 cp050039.compsig

5565ffaa96cb31f922dda10dff5abe3ef6d5639336e044636c750933daabc6e2 cp050039.exe

#### Reboot Requirement:

Reboot may be required after installation for updates to take effect and hardware stability to be maintained.

#### Installation:

Place the Smart Component in a temporary directory, then double-click it to run.

Select .install to start extracting to a temporary location on the hard drive.

Click the .install button to perform the driver installation.

点击下方"Revision History"查看历史版本及修复的相关问题：

Compatibility Release Notes **Revision History** Important Installation Instructions Enhancements

#### Version: 4.7.1.0(C) (28 Sep 2022)

##### Enhancements

##### Upgrade Requirement:

**Optional** - Users should update to this version if their system is affected by one of the documented fixes or if there is a desire to utilize any of the enhanced functionality provided by this version.

- Added SHA384 signature

#### Version: 4.7.1.0(B) (5 Nov 2021)

##### Enhancements

##### Upgrade Requirement:

**Optional** - Users should update to this version if their system is affected by one of the documented fixes or if there is a desire to utilize any of the enhanced functionality provided by this version.

- Added support for Snap5 platforms

#### Version: 4.7.1.0 (23 Apr 2021)

##### Fixes

##### Upgrade Requirement:

**Recommended** - HPE recommends users update to this version at their earliest convenience.

- Fixed branding issue