

组网及说明

前期AC运行正常，目前AC CPU利用率100%，新无线用户无法接入wifi，之前已经连接上wifi的用户访问网络缓慢

问题描述

查看配置信息

```

=====display wlan client=====
Total number of clients: 52

=====display wlan ap all=====
Total number of APs: 22
Total number of connected APs: 22

=====display cpu=====
Unit CPU usage:
  100% in last 5 seconds
  100% in last 1 minute
  100% in last 5 minutes

=====display process cpu=====
CPU utilization in 5 secs: 100.0%; 1 min: 100.0%; 5 mins: 100.0%
  JID   5Sec   1Min   5Min   Name
  ---   ---   ---   ---   ---
   1    1.5%   0.0%   0.0%   scmd
   2    0.0%   0.0%   0.0%   [kthreadd]
   3    0.0%   0.0%   0.0%   [migration/0]
   4    0.0%   0.0%   0.0%   [ksoftirqd/0]
   5    0.0%   0.0%   0.0%   [watchdog/0]
   6    0.0%   0.0%   0.0%   [migration/1]
   7   50.0%  49.5%  49.2%   [ksoftirqd/1]
   8    0.0%   0.2%   0.2%   [watchdog/1]
.....
  38    0.0%   0.0%   0.0%   [fshe]
  47   36.3%  44.3%  45.3%   [Rcv-SingleCPU0]
  48    0.0%   0.0%   0.0%   [Rcv-SingleCPU1]
  49    0.0%   0.0%   0.0%   [Tx-SingleCPU]
  52    0.0%   0.0%   0.0%   [lipc_topology]

```

过程分析

查看cpu信息主要是进程[ksoftirqd/1]和[Rcv-SingleCPU0]很高，这是与转发相关的进程。

```

interface GigabitEthernet1/0/5
port link-mode bridge
description to hexin
port link-type trunk
port trunk permit vlan all
指导客户放通相关管理与业务vlan

```

解决方法

放通相关管理与业务vlan。