



MSR设备license注册失误,如何清除并重新注册

License

骆翔

2019-10-31 发表

问题描述

MSR设备license注册失误,如何清除并重新注册

解决方法

MSR设备license注册失误,如何清除并重新注册

[H3C]dis license

Software license information

Serial Number: H56lg-M0KfQ-tChZ2-KcnJa-37tvT-vvegy-98fBE

Register Date: 2007-12-13 11:23:14

Trade Code : 213130A15C006A000001

[H3C]_

Now you enter a hidden command view for developer's testing, some commands may affect operation by wrong use, please carefully use it with our engineer's direction.

[H3C-hidecmd]license delete

Licence delete sucess

<H3C>dis license

Software license information

Serial Number:

Register Date: 0-0-0 00:00:00

Trade Code :

<H3C>reboot \需要重启

<H3C>dis license \提示license没有注册

The software has not been registered.

<H3C>license register H56lg-M0KfQ-tChZ2-KcnJa-37tvT-vvegy-98fBE \重新注册成功

Register successfully!