

Mhy the clock of S3100 reset to default value after rebooting?

李玉辉 2006-07-24 发表

It is a specification of S3100. There is no hardware clock in S3100, so the clock that y ou set by CLI cannot be saved.