

**孟维佳** 2007-02-27 发表

S9500 does not support layer-4 switching.