

知 Limitations on the Ethernet interfaces of the SR6600 RPU and LPU

管祥杰 2009-01-13 发表

What are the limitations on the Ethernet interfaces of the SR6600 RPU and LPU?

The Ethernet interfaces of SR6604/SR6608 RPU are for out-of-band network management only, but not for running services.

The four GE interfaces on an SR 6602 router and the two GE interfaces on an SR6604/SR6608 LPU are normal service interfaces.